

Diablo Canyon Fire Department

2005 Fire Responses

Date	Incident #	Type of Fire Response
2/24/05	05-009	Fire in the turnstile in Security Bldg. (see attached A/R)
3/16/05	05-014	Wildland Fire at Gun Range (see attached A/R & Eval)
7/12/05	None assigned	Improper power supply to equipment (see A/R & Evals)
11/1/05	05-048	Small fire on 140' Turb Deck (see attached A/R)
11/9/05	05-055	Admin Bldg Fire Alarm (see attached A/R and Evals)
11/23/05	05-061	Smoking electrical panel (Diesel 2-3)
12/19/05	05-066	Arcing light ballast in Admin elevator (see attached a/r)

Incident Response Log - 2005

Response Number	Response Code(s) *	Date	Description of Response	Log Entry By:	A/R Number
05-001	H	1-12-05	Hydroxime Spill U-2 Butress 1/2 TSP	DTS	A629847
05-002	M	1-12-05	43yr old Male Chest Pain/Shortness of Breath	DTS	
05-003	H	1-13-05	Main Lift Leaking Hydraulic Fluid	DTS	A0629950
05-004	F	2-2-05	SMOKE FROM CELL INCARCERATED	CP	A0631267
05-005	O	2-3-05	Broken Sprinkler head 154 Fan Room (Aux)	EC	
05-006	M	2-4-05	med Aid (Security Guard feeling weak)	EC	
05-007	F	2-18-05	FIRE ALARM, ADMIN BLDG.	BE	A0632498
05-008	H	2-22-05	Oil Spill on Unit 2 Tr Yard (not reportable)	EC	n/A
05-009	F	2-24-05	Exit Turnstyle Shorted Out - Smoke in area	DTS	A 0632916
05-010	M	3-9-05	SECURITY OFFICER WITH DIFFICULTY BREATHING	BE	
05-011	R	3-10-05	ELEVATOR RESCUE	BE	
05-012	M	3-16-05	SPLAIN ANKLE W/ABUSE 'B'	CP	
05-013	F	3-16-05	SMELL OF HOT ELECTRICAL ADMANISD	CP	
05-014	F	3-16-05	VEGETATION FIRE BEHIND GUN RANGE	CP	A0634341
05-015	M	3-21-05	CHEST PAIN	CP	
05-016	M	3-23-05	Crushed finger in door	EC	n/A
05-017	M	4-13-05	Head injury from door.	UBR	
05-018	H	4-14-05	ETA LEAK U-1 BUTRESS	CP	
05-019	M	4-14-05	SIEZURE AT EXIT TOWNHOUSE	CP	
05-020	H	4-15-05	POSSIBLE HYDROCARBON RELEASE 64' HIGH WASTE GAS COMPARTMENT	CP	

Incident Response Log - 2005

Response Number	Response Code(s) *	Date	Description of Response	Log Entry By:	A/R Number
05-021	H	4-16-05	Hydrazine Clean-up (1 QT) Unit 2 Polisher	EC	06636543
05-022	H	4-20-05	Sodium Hypochlorite SPILL IN TAKE	CP	
05-023	M	5-8-05	Medical Aid - Allergic Reaction, Difficulty Breathing	DTS	None
05-024	M/R	5-10-05	VEHICLE TC 1-7 MILE MARKER	CP	
05-025	M	5-12-05	WAGON TO STA. 2 - SCRAP LACERATION FROM AC UNIT	BE	N/A
05-026	H	5-16-05	Caustic leak Unit 1 Polisher	EC	06636327
05-027	M	5/31/05	Medical aid diabetic	CBP	
05-028	M	6/10/05	MEDICAL PRO / woman coughing & vomiting blood → Stanislaus Hospital	DL	N/A
05-029	M	6/16/05	Difficulty Breathing Control Room → AG Hospital	DL	N/A
05-030	M	6/26/05	UNKNOWN PROBLEM IN CONTROL ROOM	PK	
05-031	R	7-8-05	Elevator Rescure (Aux Bld)	EC	
05-032	M	7-9-05	Shoulder Injury from shoveling	EC	
05-033	F	7-12-05	Snake in Admin Computer Room	DTS for SE	A0642118
05-034	M	8-7-05	Med Aid (back pain) Transported to friend via SAs	EC	
05-035	H	8-10-05	Light Hypertensive on Kelp Cutters & Intake	FW	
05-036	H	8/5/05	Sewage leak west Admin	CBP	
05-037	M	8-18-05	MEDICAL @ TRAINING BUILDING - UNKNOWN PROBLEM	PK	
05-038	O	8-26-05	Vehicle rollover (5.0 mile marker) one pt tx to AGER	EC	N/A
05-039	O	8-26-05	Vehicle TC (0.5 mile marker) non-injury		
05-040	M	8-31-05	POSSIBLE REACTION TO BAG STING		N/A

* Fire Medical Hazmat Rescue Other

Incident Response Log - 2005

Response Number	Response Code(s) *	Date	Description of Response	Log Entry By:	A/R Number
05-041	H	9-7-05	Small Hypochlorite leak at WAT Facility (water)	EC	0695678
05-042	H	9-12-05	30 GAL spill 5030 VRSOL SOLUTION AT HAZ STAGE BUS W/SE AR A0645924	FW	A0645924
05-043	O	9-21-05	Non injury TC Single vehicle 1.3 mile marker	DTS	
05-044	H	10-15-05	Hydrazine Spill at the Boric Acid Injection Skid	DTS	A0698386
05-045	M	10-20-05	Medical Aid (slp ? feel) hand/knee pain	EC	n/a
05-046	M	10-28-05	MEDICAL AID - ILL (FLU) PT.	EC	n/a
05-047	M	11-1-05	Med Aid - ill pt coming out of containment (Stanks can)	EC	n/a
05-048	F	11-1-05	LP-C Rotor fire that was extinguished by Firewatch	EC	06699899
05-049	M	11-2-05	walk-in Med Fac.	MAT	
05-050	M	11-5	Sore Back walk-in	MAT	
05-051	M	11-5	nose bleed walk-in	MAT	
05-052	M	11-5	Sore Back walk-in	MAT	
05-053	M	11-6	MEDICAL AID FOREIGN OBJECT IN EYE	MAT RUSH	
05-054	M	11-8-05	MEDICAL ASSESSMENT - PT. FEELING "ILL"	EC	N/A
05-055	F	11-9-05	FIRE ALARM - ADMIN BLDG.	EC	A0650938
05-056	M	11-11-05	FIRST AID - FALL @ LOT 4 - TAKEN TO MED STG - P.V	EC	
05-057	M	11-14-05	Med Aid (laceration above eye) outside Containment	EC	n/a
05-058	M	11-14-05	Med Aid (laceration to face) sent back to work	EC	n/a
05-059	M	11-19-05	Med Aid (laceration to leg) sent back to work	EC	n/a
05-060	M	11-20-05	Med Aid (confusion to head) sent back to work	EC	n/a

* Fire Medical Hazmat Rescue Other

Incident Response Log - 2005

Response Number	Response Code(s) *	Date	Description of Response	Log Entry By:	A/R Number
05-061	F	11/23/05	FIRE (SMOKE) 2-3 DIESEL	ADC	
05-062	R	12/1/05	Vehicle T.C. (m/m 2.0)	EC	n/a
05-063	M	12.2.05	MEDICAL AID - MED. DISCOMFORT DURING SELF-DIALYSIS	JBL	
05-064	M	12-12-05	ALLERGIC REACTION @ WAREHOUSE	RR	n/a
05-065	H	12-15-05	Hydraulic Fluid Leak from Forklift at Admin Bldg	DTS	A0655840
05-066	F	12-14-05	Arcing ballast in #1 Admin Elevator	EC	A0655981
05-067					
05-068					
05-069					
05-070					
05-071					
05-072					
05-073					
05-074					
05-075					
05-076					
05-077					
05-078					
05-079					
05-080					

* Fire Medical Hazmat Rescue Other

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : Security Building Exit Turnstyle 7

INCIDENT # : 05-009

DATE : 2-24-05

DISPATCHED :

ON SCENE:

EXTINGUISHED :

AVAILABLE :

TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER Specify:

INCIDENT DATA

FIRE AREA :

FIRE ZONE :

OCCUPANCY :

FIRE ORIGIN LOCATION : Turnstile controler

BUILDING CONSTRUCTION :

EXTENT WHEN DISCOVERED : wire burned trough

EXTENT WHEN EXTINGUISHED : no smoke or fire when we arrived

CAUSE OF FIRE : short in controller

WHAT BURNED : soleloid and supply wire

ESTIMATED PROPERTY LOSS : \$200

DAMAGE TO : turnstile controller

COMMAND POST LOCATION : none

STAGING AREA : none

LIST AGENCIES NOTIFIED : none

RESPONDERS AT SCENE

FIRE OFFICERS: Stocks, Cappelluti

SAFETY PERSONNEL:

MEDICAL PERSONNEL:

BRIGADE MEMBERS:

OPERATIONS: Sturgeon

SECURITY:

OFFSITE FIRE:

OFFSITE AMBULANCE:

OTHER (SPECIFY):

ICS POSITIONS

INCIDENT COMMANDER :

SAFETY OFFICER :

SECURITY LIAISON :

OPERATIONS CHIEF :

LOGISTICS CHIEF :

PLANNING CHIEF :

STAGING OFFICER :
MEDICAL LEADER :
OTHER (Specify) :

INCIDENT REPORTING

REPORTING PARTY :

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify:

WITNESS(ES)

Name and Title :

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

none

LIST FIRE FIGHTING EQUIPMENT USED

none

NARRATIVE

Recieced via bridge line a report of a fire in the exit turnstiles in the security building. Fire fighter Cappelluti was in the area and grabbed an extinguisher and was on scene in less than a minute. He reported that there was no visible smoke or fire. There was a strong smell of electrical smoke even though there was none visible. Scott Roberts was on scene and he took the cover off of the controller box. The supply wire inside the controller box was burned through. He isolated the power to the turnstyle by removing a relay in an adjacent box and by opening the breaker to the controller. The scene was safe so we left.

A0632916

NAME : Dan Stocks DATE : 2/24/05 SIGNATURE: _____

REVIEWED BY : _____ DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : On Hill North East and above of the Security Shooting Range

INCIDENT # : 05-014

DATE : 03-16-05

DISPATCHED : 2036

ON SCENE: 2040

EXTINGUISHED : 2058

AVAILABLE :

TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER Specify:

INCIDENT DATA

FIRE AREA : Outside

FIRE ZONE :

OCCUPANCY :

FIRE ORIGIN LOCATION :

BUILDING CONSTRUCTION :

EXTENT WHEN DISCOVERED : Approx 1/4 acre

EXTENT WHEN EXTINGUISHED : Approx 1/2 acre

CAUSE OF FIRE : Tracer round shot by Security officer

WHAT BURNED : Vegetation

ESTIMATED PROPERTY LOSS : 0

DAMAGE TO :

COMMAND POST LOCATION : At the "Y" in the road just below warehouse "B"

STAGING AREA :

LIST AGENCIES NOTIFIED : CDF

RESPONDERS AT SCENE

FIRE OFFICERS: Chris Paris, Dan Stocks, Dave Schroeder, Randy Ward, Jeff Schwarz

SAFETY PERSONNEL:

MEDICAL PERSONNEL:

BRIGADE MEMBERS:

OPERATIONS:

SECURITY:

OFFSITE FIRE: Battalion 3416, E-62, E-3473, U-62

OFFSITE AMBULANCE:

OTHER (SPECIFY):

ICS POSITIONS

INCIDENT COMMANDER : Paris

SAFETY OFFICER :

SECURITY LIAISON :

OPERATIONS CHIEF :

LOGISTICS CHIEF :

PLANNING CHIEF :

STAGING OFFICER :
MEDICAL LEADER :
OTHER (Specify) :

INCIDENT REPORTING

REPORTING PARTY : Security

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify: Fire Alarm

WITNESS(ES)

Name and Title : Dave Morris, Sam Samaro Security Trainers

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

LIST FIRE FIGHTING EQUIPMENT USED

NARRATIVE

On Wednesday March 16th at 2036 the Diablo canyon fire department received a 779 fire alarm for a vegetation fire at the security department gun range. Initial conditions upon arrival were approximately ¼ acre fire with a slow to moderate rate of spread in all directions. The fire was approximately 500' above and to the south of the old leach field road. The Incident Commander requested assistance from CDF and instructed the DCPD fire department to lay a wild land hose lay and start putting out fire on the right flank. Firefighting actions started at 2048. At 2052 the right flank of fire was out and the head had bumped up against a large rock outcropping. The DCPD fire department then started up the left flank and had total extinguishment at 2058. CDF engine 62 was on scene at 2059 and assisted us with mop up activities. At 2108 CDF engine 3473 and Battalion Chief 3416 were on scene. B-3416 assisted the Incident Commander with a unified command, Engine 3473 stayed available to protect the plant. At 2210 all CDF units were released and Command was terminated.

Initial investigation of the cause of the fire is security fired a tracer round into the hill and the hill started on fire.

A0634341

NAME : Chris Paris DATE : 3-17-05 SIGNATURE: _____

REVIEWED BY : _____ DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : Unit 1 140' Turbine Deck (Low Pressure Rotor -C)
INCIDENT # : 05-048
DATE : 11-1-05
DISPATCHED : 1015 ON SCENE: 1025 EXTINGUISHED : 1010
AVAILABLE : 1015

TYPE OF INCIDENT

STRUCTURE FIRE WILDLAND FIRE VEHICLE FIRE
OTHER Specify: Small Class A fire underneath rotor

INCIDENT DATA

FIRE AREA : 14-A
FIRE ZONE :
OCCUPANCY :
FIRE ORIGIN LOCATION : Tape used on fire blanket material
BUILDING CONSTRUCTION : Concrete
EXTENT WHEN DISCOVERED : Extinguished by Firewatch
EXTENT WHEN EXTINGUISHED : Extinguished
CAUSE OF FIRE : Cutting torch slag
WHAT BURNED : tape
ESTIMATED PROPERTY LOSS : none
DAMAGE TO : n/a
COMMAND POST LOCATION : n/a
STAGING AREA : n/a
LIST AGENCIES NOTIFIED : Safety

RESPONDERS AT SCENE

FIRE OFFICERS: Carter
SAFETY PERSONNEL: n/a
MEDICAL PERSONNEL: n/a
BRIGADE MEMBERS: n/a
OPERATIONS: n/a
SECURITY: n/a
OFFSITE FIRE: n/a
OFFSITE AMBULANCE: n/a
OTHER (SPECIFY): Jim Oneill (Alston contractor rep)

ICS POSITIONS

INCIDENT COMMANDER : n/a
SAFETY OFFICER : n/a
SECURITY LIAISON : n/a
OPERATIONS CHIEF : n/a
LOGISTICS CHIEF : n/a
PLANNING CHIEF : n/a

STAGING OFFICER : n/a
MEDICAL LEADER : n/a
OTHER (Specify) : n/a

INCIDENT REPORTING

REPORTING PARTY : Alston

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify:

WITNESS(ES)

Name and Title : Firewatch (believe the last name is Joy)

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

None

LIST FIRE FIGHTING EQUIPMENT USED

(1) portable 10lb cardox extinguisher

NARRATIVE

Received a phone call that a firewatch had discharged an extinguisher on a "very small fire" while a cutting operation had been taking place in LP-C on the 140' Turb Deck. They also stated the fire was extinguished. Upon arrival, met with the contract rep (Oneill) who stated a piece of cutting slag had burned through a fire blanket, ignited some tape below. Flame size was stated to be 1"-2" in height with a base of 1"-2". The firewatch immediately did as trained and extinguished the small fire. Later found out that the slag did not burn through the fire blanket (brand is Black Velvet), but rather fell between a small opening. Work was immediately stopped by the contractor until an appropriate cause analysis could be completed. Corrective Actions were to remove all tape and attach fire blanket with wire. See a/r a0649899 for further detailed info.

NAME : Eric Carter DATE : 11-1-05 SIGNATURE: _____

REVIEWED BY : _____ DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : Administration Building

INCIDENT # : 05-055

DATE : November 9, 2005

DISPATCHED : ON SCENE:

EXTINGUISHED :

AVAILABLE :

TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER Specify: Local Bldg Alarm

INCIDENT DATA

FIRE AREA : Admin Bldg

FIRE ZONE :

OCCUPANCY :

FIRE ORIGIN LOCATION : Room 213

BUILDING CONSTRUCTION : Steel Frame, Center Core, Curtain Wall

EXTENT WHEN DISCOVERED : Detector in Alarm

EXTENT WHEN EXTINGUISHED :

CAUSE OF FIRE : Smoke from Shrink Wrap Job

WHAT BURNED : N/A

ESTIMATED PROPERTY LOSS : N/A

DAMAGE TO : N/A

COMMAND POST LOCATION : N/A

STAGING AREA : N/A

LIST AGENCIES NOTIFIED : N/A

RESPONDERS AT SCENE

FIRE OFFICERS: Chief Paris, Captain Stocks, Captain Ellis

SAFETY PERSONNEL:

MEDICAL PERSONNEL:

BRIGADE MEMBERS: Cappelluti, Wimberly, Rigby

OPERATIONS:

SECURITY:

OFFSITE FIRE:

OFFSITE AMBULANCE:

OTHER (SPECIFY):

ICS POSITIONS

INCIDENT COMMANDER : Dan Stocks

SAFETY OFFICER :

SECURITY LIAISON :

OPERATIONS CHIEF :

LOGISTICS CHIEF :

PLANNING CHIEF :

STAGING OFFICER :
MEDICAL LEADER :
OTHER (Specify) :

INCIDENT REPORTING

REPORTING PARTY : Building Alarm

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify: Alarm System

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify: Radio

WITNESS(ES)

Name and Title :

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

Administration Building Alarm system activated

LIST FIRE FIGHTING EQUIPMENT USED

Engine 9799 staged at VIS

NARRATIVE

The local fire alarm in the admin bldg sounded Wednesday afternoon, November 9, 2005 and the building was evacuated by the floor wardens. The alarm panel on the 6th floor listed the alarm as a smoke detector on the 2nd floor west. When the fire department arrived on scene, they found a smoke detector in alarm status in room 213 of the 2nd floor. The entire admin bldg was walked-down. Once an "All Clear" was given, the building alarm was silenced and a PA announcement was made giving permission to employees to re-enter the building.

Further investigation of room 213 found this room being used as a temporary electrical shop that they at times will solder and shrink wrap electrical equipment. A shrink wrap job was in progress which activated the smoke detector in the room. The shrink wrap gun was still hot and sitting within one half inch of a newspaper. The smoke and fumes associated with shrink wrapping and soldering is enough to cause the smoke detector to activate and should not be done in this room any longer. We do not want to cycle the administration building employees with false alarms as it is very unproductive, and if people get used to them they will be less inclined to evacuate the building, or worse, have a high-rise fire.

Room 213 is also in need of better housekeeping practices.

A0650938

NAME : Dave Schroeder DATE : 11-09-05 SIGNATURE: _____

REVIEWED BY : _____ DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : Unit 2....2-3 diesel
INCIDENT # : 05-061
DATE : 11-23-05
DISPATCHED : 0624 ON SCENE: 0628 EXTINGUISHED : N/A
AVAILABLE :

TYPE OF INCIDENT

STRUCTURE FIRE WILDLAND FIRE VEHICLE FIRE
OTHER Specify: Smokeing electrical panel

INCIDENT DATA

FIRE AREA : Diesels U-2
FIRE ZONE : 22 B-3
OCCUPANCY :
FIRE ORIGIN LOCATION :
BUILDING CONSTRUCTION :
EXTENT WHEN DISCOVERED : Minor
EXTENT WHEN EXTINGUISHED : Self extinguished, black and melted area from high heat only
CAUSE OF FIRE : No fire, high resistance on a connection.
WHAT BURNED : Overload Contactor for lude oil heater
ESTIMATED PROPERTY LOSS : New Contactor freedom series model CN15GN
DAMAGE TO : localized to component
COMMAND POST LOCATION : Diesel Hallway
STAGING AREA : Outside Administration Building
LIST AGENCIES NOTIFIED : None

RESPONDERS AT SCENE

FIRE OFFICERS: Paris, Frazier, Schwarz, Penner, Depew, Turner
SAFETY PERSONNEL:
MEDICAL PERSONNEL:
BRIGADE MEMBERS:
OPERATIONS:
SECURITY:
OFFSITE FIRE:
OFFSITE AMBULANCE:
OTHER (SPECIFY):

ICS POSITIONS

INCIDENT COMMANDER : Frazier / Paris
SAFETY OFFICER :
SECURITY LIAISON :
OPERATIONS CHIEF :
LOGISTICS CHIEF :
PLANNING CHIEF :

STAGING OFFICER :
MEDICAL LEADER :
OTHER (Specify) :

INCIDENT REPORTING

REPORTING PARTY :

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify: Fire Alarm

WITNESS(ES)

Name and Title :

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

LIST FIRE FIGHTING EQUIPMENT USED

CO2 fire extinguishers, none were discharged, H2O hosereel as a back up

NARRATIVE

Received notification via fire alarm and 76 conference call in regards to a smoking electrical panel in the 2-3 diesel. Fire department responded with engine and 4 firefighters. Chief Paris already at scene. Security allowed access for engine into the PA and engine was staged west of the admin building. FF's Penner and Depew entered the area to meet with Chief Paris (full SCBA). Ops de-energized the panel and FF Depew used the CO2 extinguisher to provide protection and extinguish any non-visible flames, etc in cabinet. Safety and OPS on scene, Engine released and returned to service.

NAME : Dan Frazier DATE : 11-23-05 SIGNATURE: _____

REVIEWED BY : _____ DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : Admin Building (Elevator #1)
INCIDENT # : 05-066
DATE : 12-19-2005
DISPATCHED : 1048 ON SCENE: 1055 EXTINGUISHED : 1048
AVAILABLE : 1055

TYPE OF INCIDENT

STRUCTURE FIRE WILDLAND FIRE VEHICLE FIRE
OTHER Specify: Arcing ballast in overhead elevator light

INCIDENT DATA

FIRE AREA : n/a
FIRE ZONE : n/a
OCCUPANCY : office/assembly
FIRE ORIGIN LOCATION : n/a
BUILDING CONSTRUCTION : concrete and steel
EXTENT WHEN DISCOVERED : extinguished, but energized
EXTENT WHEN EXTINGUISHED : de-energized
CAUSE OF FIRE : possible faulty ballast
WHAT BURNED : ballast
ESTIMATED PROPERTY LOSS : \$20.00
DAMAGE TO : ballast
COMMAND POST LOCATION : Lobby
STAGING AREA : not established
LIST AGENCIES NOTIFIED : CDF

RESPONDERS AT SCENE

FIRE OFFICERS: Carter, Beile, Porte, Coito, and Felix
SAFETY PERSONNEL: n/a
MEDICAL PERSONNEL: n/a
BRIGADE MEMBERS: Rick Hicks (Ops Responder)
OPERATIONS: Nimick and Schwartzbah
SECURITY: numerous
OFFSITE FIRE: CDF dispatched at 1050, but cancelled at approx 1055
OFFSITE AMBULANCE: n/a
OTHER (SPECIFY): Joe Higgins (Building Maint)

ICS POSITIONS

INCIDENT COMMANDER : Carter
SAFETY OFFICER : n/a
SECURITY LIAISON : n/a
OPERATIONS CHIEF : n/a
LOGISTICS CHIEF : n/a
PLANNING CHIEF : n/a

STAGING OFFICER : n/a
MEDICAL LEADER : n/a
OTHER (Specify) : n/a

INCIDENT REPORTING

REPORTING PARTY : Security Officer

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify:

WITNESS(ES)

Name and Title : Security Officer

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

none

LIST FIRE FIGHTING EQUIPMENT USED

E-9799, B-9769, staged hand held extinguishers

NARRATIVE

While riding Admin Building elevator #1, a Security Officer heard a pop and saw small arc's coming from the center overhead light. This was followed by light smoke and classic burnt ballast odor. Diablo Fire responded with E-9799 and B-9769, and requested CDF response via "76 bridge". After a delay at Gate 1A, we arrived on scene. The Ops Responder notified us by radio the above info and that there was no fire. Incident Commander went to scene and staged Engine personnel in the Lobby. Requested Control Room cancel CDF. I/C and Ops Responder de-energized the elevator and back up power supply (these overhead lights stay energized via back up power). I/C confirmed no residual heat in affected overhead light, plus the other two. Engine released and returned to quarters. Elevator turned over to Joe Higgins who will place signs on all doors and contact the vendor for repairs.

A0655981

NAME : Eric Carter DATE : 12-19-05 SIGNATURE: _____

REVIEWED BY : _____ DATE : _____