

# Diablo Canyon Fire Department

## 2006 Fire Responses

Date	Incident #	Type of Fire Response
3/12/06	None assigned	Smell of Smoke (128' Cable Spreading Rm.) (A/R only)
4/29/06	06-026	Smoldering KIMWIPE at Chem Lab (see attached A/R)
5/5/06	None assigned	Fire near Feedwater pp 2-2 (see A/R & Eval only)
9/5/06	06-046	Fire Alarm (6 <sup>th</sup> floor Admin) (see attached A/R)
10/3/06	06-049	Smell of smoke in Aux Bldg (see attached A/R)
12/12/06	06-056	Fire at Intake CWP 2-1 (see attached A/R)

# Incident Response Log - 2006

Response Number	Response Code(s) *	Date	Description of Response	Log Entry By:	A/R Number
06-001	H	1-12-06	Battery Acid Spill on Road to N16 Warehouse	EC	N/A
06-002	M	1-17-06	Med Aid 6th Floor Ashbin (PT tx by SLAS)	EC	N/A
06-003	O	2-3-06	UTILITY CABET ROLLER @ NPT WAREHOUSE; EXTRACTION REQ'd	BE	N/A
06-004	M	2-09-06	MEDICAL RESPONSE TO SIM DIZZINESS LOW BP	JK	N/A
06-005	M	02-09-06	MED - MAIN WAREHOUSE CHEST PAIN	JK	N/A
06-006	M	02-09-06	MED - LOT 6 SPRAINED ANKLE	JK	N/A
06-007	M	02-09-06	MED - SHOOTING RANGE BROKE TIB FIB	JK	N/A
06-008	F	03-12-06	SMOKING (POWER SUPPLY) (COMPUTER C.A.C.O) CHAIR SPRINGING FROM U-1 ARE WRITTEN	JK	AG661658
06-009	H	3-17-06	BOMBAY ACID SPILL N/A GATE 1	JK	AG662025
06-010	F	3-17-06	SMOKING CIGARETTE OUT CONTAINER	JK	N/A
06-011	M	3-30-06	Med Aid (Back pain) 2nd Floor Ashbin	PEC	N/A
06-012	H	4-2-06	HYPERAZIONE CEMEX - U-1 85' BORIC ACID ARE	PEC	N/A
06-013	M	4-12-06	Med Aid (Stomach pain) PT refused Tx or Transport	EC	N/A
06-014	H	4-20-06	BATTERY ACID IN 2-2 CIRCULAR TUNNEL	PEC	N/A
06-015	M	4-18	Med Fac cut hand (minor)	MATE	No
06-016	M	4-18	Med Fac cut Forearm (minor)		
06-017	M	4-19	Med Fac Rash (Tunnels)		
06-018	M	4-19	Med Fac Abd pain		
06-019	M	4-21-06	Med Fac slipped on stairs		
06-020	M	4-27-06	Med Aid (knee pain) slip & fall on stairs	EC	N/A

Diablo Canyon Fire Department  
**Incident Response Log - 2006**

Response Number	Response Code(s) *	Date	Description of Response	Log Entry By:	A/R Number
06-021	M		CONTAINMENT HEAT STRESS	PT	
06-022	M	4-26-06	Med Fac Lee (C) Hand	MAT	N
06-023	F	4-27-06	Butt can fire no response, no report	MAT	N
06-024	H	4-28-06	HYDRAULIC OIL SPILL @ RESERVOIR ROAD	BS	A0665498
06-025	H	4-29-06	HYDRAULIC OIL SPILL - URBAN MOBILE CRANE, 140' RCA	BS	A0665556
06-026	F	4-30-06	Smell of smoke (85' Chem lck) Concealed smoke by O/S responder <small>smothering explosion on last plate</small>	EC	A0665631
06-027	M	5-3-06	Knee injury at Intake	MP	N
06-028	F	5-5-06	SMALL FIRE @ FUEL PUMP 2-2, EXTINGUISHED BEFORE ARRIVAL	BS	A0666367
06-029	M	5-12-06	Crushed Finger	MAT	-
06-030	M	5-13-06	Possible miss carriage	R	-
06-031	M	5-13-06	KNEE INJURY	R	-
06-032	M	5-16-06	Caustic splash to face	MAT	-
06-033	H	5-16-06	CO <sub>2</sub> DISCHARGE # 10 REARBY UNIT 2 TURBINE	EC	-
06-034	M	5-19-06	Ruptured bag of explosive material @ workhouse; exposure	EC	-
06-035	M	5-20-06	TRAIN-LEAK - PIPE PACK - 02	DTF	-
06-036	M	6/13/06	Knee injury @ shooting range.	CBP	-
06-037	M	6/14/06	LACERATED FINGER	EC	-
06-038	H	6/16/06	TURBINE LUBE OIL ROOM 0-2 minor leak more accurate	EC	-
06-039	M	6-25-06	Minor med Aid (Cold machine Shop) Unit 1	EC	-
06-040	H	7-25-06	Lube Oil Spill U-1 Centrifuge 10 gallons	DTS	A0674054

# Incident Response Log - 2006

Response Number	Response Code(s) *	Date	Description of Response	Log Entry By:	A/R Number
06-041	H	8/9/06	Incidental hydraulic leak clean up	ESL	N/A
06-042	M	8/17/06	Standby at Medical Facility to assist with Chest Pains	Frazier	N/A
06-043	M	8/21/06	BROKEN FINGER - OPERATOR NE CORNER Admin. Bldg	BECKE	N/A
06-044	M	8/21/06	Male Passed out in Admin Elevator	DTS	NA
06-045	M	8/25/06	LIGHT HEADED IN STAIRWELL BLDG	DAS	NA
06-046	F	9-5-06	Alarm Activation Administration Building. Smoke detector 6th Floor Computer Room	DTS	A0676915
06-047	TC	9-16-06	Motorcycle vs deer at 10 mile marker	DTS	N/A
06-048	M	9-22-06	LAERATION ON TOP OF LEFT INDOOR FANS ON 3/4 X 1/2"	CLW	N/A
06-049	F	9/13/06	Smell of smoke in aux Bldg (smoked left in fan)	EC (A067776)	
06-050	H	10/3/06	Small hydraulic leak (W1 Polisher)	EC	N/A
06-051	F	10/27/06	FIRE ALARM 6TH FLOOR Admin Bldg "FALSE"	ESL	N/A
06-052	M	11/27/06	SMOKE DETECTOR ACTIVATION TO LEFT ELBOW AREA FROM TUNNEL SCRAPING	EW	N/A
06-053	M	12/2/06	Boss sprained wrist and on a D/E 2 temp employee	EC	N/A
06-054	H	12/8/06	O.I. seen by U2 spare Tx	EC	N/A
06-055	M	12/11/06	PT. CG 905, 1028 DISCOMFORT	DR	N/A
06-056	F	12-12-06	ELECTRICAL FIRE COMP 2-1	ESL	A06824405
06-057	H	12-14-06	INCIDENTAL HAZ MAT U-2 LUBE OIL ROOM oil overflow	ESL	N/A
06-058	H	12-22-06	SULFURIC ACID SPEC @ POLISH BOTTLES U-2	DR	N/A
06-060					

# DIABLO CANYON POWER PLANT

## FIRE INCIDENT REPORT

## INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : 85' Rad Access Chem Lab

INCIDENT # : 06-026

DATE : 4-29-06

DISPATCHED : 0830

ON SCENE: 0834

EXTINGUISHED : no fire

AVAILABLE : 0834

### TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER  Specify: Smoldering KIMWIPE (paper towel)

### INCIDENT DATA

FIRE AREA :

FIRE ZONE :

OCCUPANCY :

FIRE ORIGIN LOCATION : n/a

BUILDING CONSTRUCTION : Concrete/Steel

EXTENT WHEN DISCOVERED : smoldering

EXTENT WHEN EXTINGUISHED : small area of char on KIMWIPE

CAUSE OF FIRE : smoldering caused by KIMWIPE on a hot plate

WHAT BURNED : nothing

ESTIMATED PROPERTY LOSS : none

DAMAGE TO : nothing

COMMAND POST LOCATION : not established

STAGING AREA : n/a

LIST AGENCIES NOTIFIED : n/a

### RESPONDERS AT SCENE

FIRE OFFICERS: Carter, Turner

SAFETY PERSONNEL: none

MEDICAL PERSONNEL: none

BRIGADE MEMBERS: Claridy

OPERATIONS: none

SECURITY: numerous

OFFSITE FIRE: n/a

OFFSITE AMBULANCE: n/a

OTHER (SPECIFY): chem techs and rp techs

### ICS POSITIONS

INCIDENT COMMANDER : not established

SAFETY OFFICER : n/a

SECURITY LIAISON : n/a

OPERATIONS CHIEF : n/a

LOGISTICS CHIEF : n/a

PLANNING CHIEF : n/a

STAGING OFFICER : n/a  
MEDICAL LEADER : n/a  
OTHER (Specify) : n/a

### **INCIDENT REPORTING**

REPORTING PARTY : chem tech

CONTROL ROOM NOTIFIED

No  Yes  VIA: Phone  779  Other  Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No  Yes  VIA: Phone  Pager  PA  Other  Specify: radio

WITNESS(ES)

Name and Title :

### **LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED**

None

### **LIST FIRE FIGHTING EQUIPMENT USED**

None

### **NARRATIVE**

Responded to a smoke odor in the 85' Chem Lab. Ops contacted us via radio as they mishandled the initial 779 call, thus dropping it and the fire alarm only sounded for about three seconds. Contacted Security via 3330 to let them know we were responding Code 3 and would need the gates opened. They were ready when we arrived. While enroute, was contacted via the Control Room that we could cancel our response per the Ops Responder, the smoke odor was from a KIMWIPE that was left on a hot plate/stirrer used for determining pH of a liquid in a beaker. There was no fire - just a little charring on the KIMWIPE. Fire Captain continued in for investigation / report purposes and cancelled Engine that was approaching Gate 1. Confirmed there was no fire and they did place the charred KIMWIPE under running water just to be sure. Chemistry wrote the a/r and I added the above info. See a/r a0665631 for further Chemistry info.

After the response was over, the Control Room tested the fire alarm just to be sure the initial alarm problem was caused by them and not the system. We notified Security that we would be conducting a Fire Alarm test. Test was performed. Everything worked as designed.

---

---

NAME : Eric Carter                      DATE : 4-29-06                      SIGNATURE: \_\_\_\_\_

REVIEWED BY : \_\_\_\_\_                      DATE : \_\_\_\_\_

# DIABLO CANYON POWER PLANT

## FIRE INCIDENT REPORT

## INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : Computer room on the sixth floor of Admin Bldg.

INCIDENT # : 06-046

DATE : 09-05-06

DISPATCHED :

ON SCENE:

EXTINGUISHED :

AVAILABLE :

### TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER  Specify: Fire Alarm Activation. No fire.

### INCIDENT DATA

FIRE AREA : computer room sixth floor

FIRE ZONE : computer room sixth floor

OCCUPANCY : high rise office

FIRE ORIGIN LOCATION : na

BUILDING CONSTRUCTION :

EXTENT WHEN DISCOVERED : na

EXTENT WHEN EXTINGUISHED : na

CAUSE OF FIRE : no fire found

WHAT BURNED : nothing

ESTIMATED PROPERTY LOSS : 0

DAMAGE TO : none

COMMAND POST LOCATION : W. of Admin Bldg.

STAGING AREA : W. of Admin Bldg.

LIST AGENCIES NOTIFIED : CDF

### RESPONDERS AT SCENE

FIRE OFFICERS:

SAFETY PERSONNEL: none

MEDICAL PERSONNEL: none

BRIGADE MEMBERS: Dan Stocks, Dan Frazier, Tony Cappelluti, Mark Turner, Randy Ward

OPERATIONS: Mike Quidder

SECURITY:

OFFSITE FIRE: none

OFFSITE AMBULANCE: none

OTHER (SPECIFY):

### ICS POSITIONS

INCIDENT COMMANDER :

SAFETY OFFICER :

SECURITY LIAISON :

OPERATIONS CHIEF :

LOGISTICS CHIEF :

PLANNING CHIEF :

STAGING OFFICER :  
MEDICAL LEADER :  
OTHER (Specify) :

**INCIDENT REPORTING**

REPORTING PARTY :

CONTROL ROOM NOTIFIED

No  Yes  VIA: Phone  779  Other  Specify:

Notified by Security  
Watch Commander

INDUSTRIAL FIRE OFFICER NOTIFIED :

No  Yes  VIA: Phone  Pager  PA  Other  Specify:

779 Fire alarm  
sounded

WITNESS(ES)

Name and Title :

**LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED**

Sixth floor computer room local alarm and main sixth floor fire alarm panel.

**LIST FIRE FIGHTING EQUIPMENT USED**

Partol and Engine staged but not used.

**NARRATIVE**

THE FIRE DEPARTMENT RESPONDED TO A FIRE ALARM ACTIVATION AND REPORTED LIGHT SMOKE WITH AN ELECTRICAL SMELL ON THE SIXTH FLOOR OF THE ADMINISTRATION BUILDING. CDF WAS NOTIFIED OF THE RESPONSE BY THE SHIFT MANAGER. UPON ARIVIAL FOUND AN ACTIVATED SMOKE DETECTOR IN THE SIXTH FLOOR COMPUTER ROOM. THERE WAS NO SIGN OF SMOKE OR FIRE. THERE WAS NO UNUSAL SMELL IN THE ROOM. THE ROOMS WERE SEARCHED IN THE AREA AND NOTHING UNUSUAL WAS FOUND. THE ALARM WAS RESET. CDF WAS NOTIFIED THAT NOTHING WAS FOUND.

*A0676915*

NAME : Dan Stocks

DATE : 9-05-06

SIGNATURE: \_\_\_\_\_

REVIEWED BY : \_\_\_\_\_

DATE : \_\_\_\_\_

# DIABLO CANYON POWER PLANT

## FIRE INCIDENT REPORT

## INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : 140' Aux Bld

INCIDENT # : 06-049

DATE : 10/3/06

DISPATCHED : 0220

ON SCENE: 0228

EXTINGUISHED : n/a

AVAILABLE : 0230

### TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER  Specify: "heavy smell of smoke in Aux Bld"

### INCIDENT DATA

FIRE AREA : n/a

FIRE ZONE : n/a

OCCUPANCY : n/a

FIRE ORIGIN LOCATION : n/a

BUILDING CONSTRUCTION : Concrete and Steel

EXTENT WHEN DISCOVERED : n/a

EXTENT WHEN EXTINGUISHED : n/a

CAUSE OF FIRE : n/a

WHAT BURNED : n/a

ESTIMATED PROPERTY LOSS : fan belt

DAMAGE TO : fan belt

COMMAND POST LOCATION : Door 128

STAGING AREA : n/a

LIST AGENCIES NOTIFIED : n/a

### RESPONDERS AT SCENE

FIRE OFFICERS: Carter, Beile, Coito, Felix, and Porte

SAFETY PERSONNEL: n/a

MEDICAL PERSONNEL: n/a

BRIGADE MEMBERS: n/a

OPERATIONS: Gurney, Hurlburt,

SECURITY: numerous

OFFSITE FIRE: cancelled enroute

OFFSITE AMBULANCE: n/a

OTHER (SPECIFY): n/a

### ICS POSITIONS

INCIDENT COMMANDER : Carter

SAFETY OFFICER : Carter

SECURITY LIAISON : not established

OPERATIONS CHIEF : not established

LOGISTICS CHIEF : not established

PLANNING CHIEF : not established

STAGING OFFICER : not established  
MEDICAL LEADER : not established  
OTHER (Specify) : not established

**INCIDENT REPORTING**

REPORTING PARTY : Ops watch  
CONTROL ROOM NOTIFIED

No  Yes  VIA: Phone  779  Other  Specify: unknown

INDUSTRIAL FIRE OFFICER NOTIFIED :

No  Yes  VIA: Phone  Pager  PA  Other  Specify: alarm

WITNESS(ES)

Name and Title :

**LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED**

none

**LIST FIRE FIGHTING EQUIPMENT USED**

Engine, Patrol, SCBAs

**NARRATIVE**

At approx 0220, responded to a "heavy smell of smoke in the Aux Bld". Immediately had the Ops Responder respond to the Aux Bld to give me a report on conditions from a safe area. CDF requested. Upon arrival in front of the Med Facility with 9799 and 9769, Ops Responder reported to us via radio that the smoke was from a belt on fan S-32, there is no fire, power had been DC'd to the fan, and the belt was removed. CDF cancelled. Sent in Capt Beile and FF Coito to face-to-face with the Ops Responder. Once they arrived, they confirmed that no emergency exists. Returned to quarters.

Additional Note: Upon arrival to the VIS, we were held so Security could do a cursory search of both vehicles. In my estimation, this delayed us by approx 90 seconds. We were also held at Gate 1 for an additional estimation of approx 90 seconds. I spoke with the WC after the incident and he stated this should not have happened, and he would check with his officers as to why they performed a cursory search.

A0678796

---

---

NAME : Eric Carter                      DATE : 10/3/06                      SIGNATURE: \_\_\_\_\_

REVIEWED BY : \_\_\_\_\_                      DATE : \_\_\_\_\_

# DIABLO CANYON POWER PLANT

## FIRE INCIDENT REPORT

## INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : Intake Structure CWP 2-1

INCIDENT # : 06-056

DATE : 12-12-06

DISPATCHED : 1328

ON SCENE: 1331

EXTINGUISHED : 1358

AVAILABLE :

### TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER  Specify:

### INCIDENT DATA

FIRE AREA :

30-A-5

FIRE ZONE :

OCCUPANCY :

FIRE ORIGIN LOCATION :

Inside CWP 2-1 Motor Housing

BUILDING CONSTRUCTION :

Concrete

EXTENT WHEN DISCOVERED :

3 to 4 inch flames in vicinity of main lead box

EXTENT WHEN EXTINGUISHED :

completely extinguished

CAUSE OF FIRE :

possible overcurrent. TBD

WHAT BURNED :

electrical insulation

ESTIMATED PROPERTY LOSS :

estimated 100,000 to 500,000

DAMAGE TO :

CWP 2-1

COMMAND POST LOCATION :

Intake parking lot

STAGING AREA :

Warehouse B

LIST AGENCIES NOTIFIED :

CDF

### RESPONDERS AT SCENE

FIRE OFFICERS:

Dave Schroeder, Scott Ellis

SAFETY PERSONNEL:

John Beymer

MEDICAL PERSONNEL:

BRIGADE MEMBERS:

Nick Depew, Randy Ward, Jeff Schwarz, Mark Penner

OPERATIONS:

James Ewart

SECURITY:

Bill Gibson

OFFSITE FIRE:

CDF 3416 / E62 / E63 / E21 / R21 / Breathing Support

OFFSITE AMBULANCE:

OTHER (SPECIFY):

### ICS POSITIONS

INCIDENT COMMANDER :

Chris Paris

SAFETY OFFICER :

John Beymer

SECURITY LIAISON :

Bill Gibson

OPERATIONS CHIEF :

Dave Schroeder

LOGISTICS CHIEF :

PLANNING CHIEF :

STAGING OFFICER :  
MEDICAL LEADER :  
OTHER (Specify) :

**INCIDENT REPORTING**

REPORTING PARTY : Intake Watch

CONTROL ROOM NOTIFIED

No  Yes  VIA: Phone  779  Other  Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No  Yes  VIA: Phone  Pager  PA  Other  Specify:

WITNESS(ES)

Name and Title :

**LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED**

No evidence of CO2 discharge.

**LIST FIRE FIGHTING EQUIPMENT USED**

Lines pulled from E9799. Fire extinguished with hose line.

**NARRATIVE**

Fire department initially notified via phone call to station. CDF was requested. Fire department had begun response when fire alarm was sounded. Upon arrival, checked with Security for accountability. Area determined to be clear. Mech Maint was on scene and asked if we wanted a hatch removed for ventilation purposes. Mech Maint was given the go ahead to remove the hatch. Command post established at Intake parking lot. Lines were pulled from E9799 and extended down the south staircase into the Intake structure. Capt Ellis and FF Penner were the initial entry team. Entry team conducted primary search. Before entering CWP 2-1 Motor Housing, FF Penner's low air warning activated. It was determined to be an unknown leak. Entry team was replaced with FF's Depew and Ward who followed the hose line in to the CWP 2-1 Motor Housing. Upon entering the housing they saw 3 to 4 inch flames coming from the area of the main lead box. Motor was verified de-energized and approximately 4 gallons of water was used to extinguish the flames. The rest of the motor was checked for extension. No extension found. Fire was completely extinguished. Reflash watch was established for an additional 30 minutes. CDF personnel were utilized to assist with ventilation efforts. Air was monitored to determine level of safety. Initial CO readings were high, but then rapidly dropped into the single digits. Ops made entry into CWP 2-2 to attempt to start it. Fire Department stood by while attempt was made. After attempts failed, all resources were released and command was terminated

AD684405

NAME : Dave Schroeder      DATE : 12-12-06      SIGNATURE: \_\_\_\_\_

REVIEWED BY : \_\_\_\_\_      DATE : \_\_\_\_\_