

Diablo Canyon Fire Department

2008 Fire Responses

Date	Incident #	Type of Fire Response
1/22/08	08-013	Smell of smoke (Trailer 220) - No report
2/11/08	08-022	Fire alarm (Building 102) - No report
2/18/08	08-025	Heavy smoke (U2 Buttress)
2/19/08	08-028	Fire alarm (4 th Floor Admin)
3/11/08	08-038	Smoking butt can (Crane Bay)
3/13/08	08-039	Smoking butt can (U2 Buttress)
5/6/08	08-054	Alarm sounding (I&C Building)
6/9/08	08-059	Fire in U1 Turbine Building (140')
6/29/08	08-060	Heavy smoke (6 th Floor Admin)
7/18/08	08-065	Smoke in kitchen (5 th Floor Admin)
8/16/08	08-070	Transformer fire (U2 Transformer Yard)
8/26/08	08-073	Smoke alarm (Penthouse)
9/12/08	08-078	Fire alarm (6 th Floor Admin)
9/18/08	08-079	Fire alarm (I&C Building)
11/10/08	08-084	Fire in U1 PPC Room
11/12/08	08-086	Fire in dirty lube oil room
11/19/08	08-087	Fire alarm (Cold Machine Shop)
12/9/08	08-088	Electrical fire (Haz Waste Building)
12/10/08	08-090	Vehicle Fire (Lot 1)

Diablo Canyon Fire Department
Incident Response Log - 2008

Response Number	Response Code(s) *	Date	Description of Response	Log Entry By:	A/R Number
08-001	M	1/5/08	FAM VICTIM (STAFFORD) @ TRAVE BLDG WITH SGT	DR	-
08-002	M	1/6/08	WALK W @ FIRE STATION - HAND LACERATION	RHW	
08-003	M	1-7-08	MAN DOWN WAREHOUSE BRADNO non TRANSPORT		
08-004	M				
08-005	M	1-14-08	ABDOMINAL PAINS WHITE B SGT WORKER		
08-006	M	1-15-08	Diabetic ON-site	MAT	
08-007	FA	1-11-08	FALSE ALARM 7TH Floor Annular Bldg		
08-008	HM	1-17-08	RED VAP BUG LEAKING FULL LOT 4		
08-009	M	1-17-08	MEDICAL AIO Ann Bldg 3RD Floor - Female to S.U Hospital		
08-010	M	1-18-08	MEDICAL SEC BLDG MALE/TINGLING HANDS/TO SV HOSP.	EW	
08-011	ME	1-19-08	MEDICAL >??- IMF - MALE (EYE FLUWS RELEASED ^{RELEASED} REARIS TO WORK PLW		
08-012	M	1-21-08	medical via pager (Security Guard feeling unwell)	EC	
08-013	F	1-22	TRF 220 ALC smell of smoke	MAT	N/A
08-014	M	1-23	CHEST PAIN / PT TRANSPORTED SEESITE		
08-015	M	1-24	DIZZINESS		
08-016	M	1/25/08	WALK IN @ FIRE STATION NUMBNESS @ FEET	RHW	N/A
08-017	M	1/29/08	Pa. Pass injured knee at base of stairs to lot 6	EC	N/A
08-018	M	2-3-08	Slip & fall at SGT warehouse B - lower back pain		
08-019	M	2-4-08	SOB Medical White B		
08-020	M	2-10-08	BACK STRAIN	Thompson	

Incident Response Log - 2008

Response Number	Response Code(s) *	Date	Description of Response	Log Entry By:	A/R Number
08-021	M	2-10-08	FOREIGN BODY IN EYE	EC	
08-022	F	2-11-08	ALARM IN BLDG 102 - NO FIRE	EC	
08-023	M	2-17-08	CHEST PAIN AMBULANCE OFF SITE	EC	
08-024	M	2-17-08	LACERATION ON LOWER LIP	GMP	
08-025	F	2-18-08	HEAVY SMOKE UNIT 2 BUTRESS - FAKE ALARM	EC	AP719989-01
08-026	M	2-19-08	Med Aid (Nausea) Unit 2 904 TBS NW	EC	
08-027	M	2-19-08	Assisted med fac with walk in chest pain (see med report)	EC	
08-028	F	2-17-08	Responded to smoke in 4th floor Admin (called by STAFF)	EC	
08-029	M	2-23-08	FOREIGN BODY IN EYE / SENT OFFSITE	EC	
08-030	M	2-23-08	TWISTED ANKLE ON INTAKE / TAKEN OFFSITE	EC	
08-031	M	2-24-08	Laceration on hand	EC	n/A
08-032	M	2-25-08	LACERATION ON RIGHT RING FINGER	GMP	N/A
08-033	M	2-26-08	Foreign body in eye @ mede firing range AMMA signed	EC	n/A
08-034	M	2/27/08	LIGHT HEADED on 91' OF CONTAINMENT	EC	
08-035	R	3/1/08	Elevator Rescure (Admin #1)	EC	
08-036	M	3/2/08	(0600) Foreign body in eye (walk in to station)	EC	
08-037	M	3/9/08	Walk-in @ mede (Light headedness / wear)	EC	
08-038	F	3/11/08	SMOKING BUTT CAN OUTSIDE U2 BUTRESS	EC	
08-039	F	3-13-08	Small aerosol butt can outside north entrance U-2 Building	EC	N/A
08-040	H	3-13-08	Haz. Material Bldg #120 - unknown liquid spill	EC	N/A

Incident Response Log - 2008

Response Number	Response Code(s) *	Date	Description of Response	Log Entry By:	A/R Number
08-041	M	3-16-08	MEDICAL @ MF - PT cut finger on trip off	EW	
08-042	F	3-16-08	91' x 110' U-2 Contaminant e vac. due to acetylene gas	EC	A0723853
08-043	M	3/16/08	EYE INJURY (FERROUS OBJECT)	TD	
08-044	D	3-20-08	Motorcycle Accident (0400) Non Injury (AMA signed)	EC	n/a
08-045	D	3-20-08	Motorcycle Accident (0600) Non Injury (AMA signed)	EC	n/a
08-046	M	3-25-08	Poss fainting pt @ 140' step off pad	EC	n/a
08-047	M	3-25-08	Poss chest pain (m/m 3.1) on Access Rd (AMA signed)	EC	n/a
08-048	M	3-26-08	SIGNIFIABLE EPISODE & LARSENATION TO CHIEF CHIEF	RLW	
08-049	F	3-27-08	Alarm sounded for a tip-over (very slow) motorcycle accident	EC	n/a
08-050	M	3-31-08	DIABETIC EMERGENCY IN CAFETERIA	EC	n/a
08-051	M	3-31-08	Elevated HR @ Desimetry office	EC	n/a
08-052	O	4-4-08	QUIT CAN SMOODERING	EC	n/a
08-053	H	4-7-08	Hydrozene leak (w/ Tank) under stairs (Oppl on meter)		
08-054	F	5-6-08	Alarm Sounding (I.i.c)	EC	A0729537
08-055	M	5-6-08	Med Aid @ Simulator	EC	n/a
08-056	M	5-14-08	MED AID @ INTAKE (ASSESSMENT ONLY)	EC	N/A
08-057	M/H	5-15-08	Motorcycle Leaking Gasoline	DTS for DJB	
08-058	O	5-20-08	Standby for Met Tower Incident	DTS	A0730749
08-059	F	6-9-08	REPORTED FIRE U1 140 TUBE / STAND BY TO RESCUE FAN	RLW	N/A
08-060	F	6-29-08	Alarm Sounding (Admin 6 th Floor) (A/C Bell)	EC	A0733889

Diablo Canyon Fire Department
Incident Response Log - 2008

Response Number	Response Code(s) *	Date	Description of Response	Log Entry By:	A/R Number
08-061	M	7/2/08	med Aid - Chest pain 3rd Floor Admin	EC	n/a
08-062	M	7/4/08	BURPED KNEE in control room	DMS	n/a
08-063	M	7/7/08	MED AID / SYNCOPY IN CONTROL ROOM	JW	N/A
08-064	M	7-17-08	med Aid - Low B/P - feeling ill in Sm. Bldg	EC	n/a
08-065	F	7-18-08	Smoke in Admin 5th Floor kitchen	EC	n/a
08-066	R	7-22-08	2 People trapped in Aux Elevator	DTS	N/A
08-067	H	7-25-08	2-4oz. of Diesel leaked from truck at VIS	DTS	A0736280
08-068	M	8-5-08	Security Personel Fell hit chin	GAF	
08-069	M	8-14-08	SECURITY GUARD DISLOCATED SHOULDER AT RANGE	JJS	
08-070	F	8-16-08	Unit 2 main Bank "C" Tx Fire	EC	A0730990
08-071	M	8-17-08	med facility walk in eye glass in left eye	GMP	N/A
08-072	M	8/21/08	TC & MILEMAKER 2.3 (VEHICLE OVER-SIDE)	AD	n/p
08-073	F	8/26/08	Smoke Alarm Penthouse Admin Building P115	DTS	A0739322
08-074	M	8/29/08	Lithium hydroxide spilled on High	EC	n/a
08-075	M	8-20-08	TWISTED ANKLE - VZ XFER YARD	DBZ	NA
08-076	M	9-2-08	Possible heat stress (patient light headed)	WP	N/A
08-077	M	9-3-08	Possible Allergic reaction	J	N/A
08-078	F	9-12-08	FIRE ALARM, ADMIN BLDG 6TH FLOOR	DBZ	N/A
08-079	F	9-18-08	Fire alarm NC Bldg 2nd Fl. duct detector	DTS	N/A
08-080	D	9-19-08	VEHICLE TC @ 2.5 MILE MAKEUP - TRANSFER DUMP RIG LOST IT BACK TRUCK	RWJ	N/A

* Fire Medical Hazmat Rescue Other

Incident Response Log - 2008

Response Number	Response Code(s) *	Date	Description of Response	Log Entry By:	A/R Number
08-081	D	11-26-08	CO ₂ LEAK 10 U2 12KV SWITCHGEAR RM	R/WB	
08-082	H	10-6-08	Hydraulic Fluid leak on Kelp Harvester	DTS	
08-083	M	10-27-08	Med Aid (back pain @ warehouse B)	EC	N/A
08-084	F	11-10-08	Smoking Transformer U1 PPG ROOM	DTS	50084363
08-085	M	11-12-08	HEADACHE MAINT. SHOP BLDG	JS	N/A
08-086	F	11-12-08	FIRE IN DIRTY LUBE OIL - FOLDING FAN	DMSA	N/A
08-087	F	11-19-08	SMOKE ALARM LOAD MACHINE SHOP	DMSA	N/A
08-088	F	12-9-08	Poss Fire H ₂ waste (Arc 10)	EC	N/A
08-089	H	12-9-08	Poss Winterygreen smell 119 TB - (UTL)	EC	N/A
08-090	F	12-10-08	Poss Vehicle Fire (Lot 1) - broken radiator/steam	EC	N/A
08-091	M	12-23-08	Med Aid (Poss broken ankle Lot 7 - fell out of box)	EC	N/A
08-092	H	12-29-08	Sulfuric Acid Spill (U1 Polisher) Incubator	EC	
08-093					
08-094					
08-095					
08-096					
08-097					
08-098					
08-099					
08-100					

* Fire Medical Hazmat Rescue Other

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : Roof or Unit 2 Butress

INCIDENT # : 08-025

DATE : 2-18-08

DISPATCHED :

ON SCENE:

EXTINGUISHED :

AVAILABLE :

TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER Specify: no fire false alarm

INCIDENT DATA

FIRE AREA : no fire false alarm

FIRE ZONE : no fire false alarm

OCCUPANCY : no fire false alarm

FIRE ORIGIN LOCATION : no fire false alarm

BUILDING CONSTRUCTION : no fire false alarm

EXTENT WHEN DISCOVERED : no fire false alarm

EXTENT WHEN EXTINGUISHED : no fire false alarm

CAUSE OF FIRE : no fire false alarm

WHAT BURNED : no fire false alarm

ESTIMATED PROPERTY LOSS : no fire false alarm

DAMAGE TO : no fire false alarm

COMMAND POST LOCATION : no fire false alarm

STAGING AREA : no fire false alarm

LIST AGENCIES NOTIFIED : no fire false alarm

RESPONDERS AT SCENE

FIRE OFFICERS: Chief Paris, Captain Stocks, Firefighters Wimberly and Felix

SAFETY PERSONNEL: John Beymer

MEDICAL PERSONNEL: none

BRIGADE MEMBERS: none

OPERATIONS: John Macintyre, Bob Arellano, Jim Bambus

SECURITY:

OFFSITE FIRE: Requested then Cancelled

OFFSITE AMBULANCE: none

OTHER (SPECIFY):

ICS POSITIONS

INCIDENT COMMANDER : Stocks

SAFETY OFFICER :

SECURITY LIAISON :

OPERATIONS CHIEF :

LOGISTICS CHIEF :

PLANNING CHIEF :

STAGING OFFICER :
MEDICAL LEADER :
OTHER (Specify) :

INCIDENT REPORTING

REPORTING PARTY :

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify:

WITNESS(ES)

Name and Title :

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

None

LIST FIRE FIGHTING EQUIPMENT USED

none

NARRATIVE

The fire alarm was sounded for a report of heavy smoke coming from the Unit 2 Buttress. Fire Officer on the bridge requested Cal Fire to respond. The on duty captain (Captain Beile) and firefighters (Captain Frazier, Fire fighters Cappelluti, and Turner) were responding from Station 97 with fire equipment. The daytime staffing firefighter (Firefighter Wimberly) and one of the duty firefighters (Firefighter Felix) were near the area and responded to the scene. The day time staffing captain (Captain Stocks) also responded to the scene. By the time Captain Stocks arrived in scene Firefighter Wimberly had walked down the inside of the first floor of the Buttress. He did not find any signs of smoke or fire. Firefighter Felix was walking down the second floor of the Buttress with Jim Bambus from Operations. They also reported no sign of smoke or fire. They reported a light smell of diesel exhaust. There was visible diesel exhaust coming from a high pressure hydro machine being used for chemical cleaning of the Unit 2 Lube Oil System. All incoming Cal Fire Units and DCPD Fire Units were cancelled. The hydro machine is located just north of the Unit 2 Buttress. The exhaust from the hydro machine is being piped south to the middle of the buttress roof. The exhaust pipe is not visible from the ground so it looks as if the exhaust is smoke coming from the roof. See AR A0719929.

NAME : Daniel T. Stocks DATE : 2-18-08 SIGNATURE: _____

REVIEWED BY : _____ DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : 4th Floor Admin Building
INCIDENT # : 08-027023
DATE : 2/19/08 ^{0752/23/20}
DISPATCHED : 1910 ON SCENE: 1910 EXTINGUISHED : 1910
AVAILABLE : 1920

TYPE OF INCIDENT

STRUCTURE FIRE WILDLAND FIRE VEHICLE FIRE
OTHER Specify: Smoke coming from a Hayworth Panel

INCIDENT DATA

FIRE AREA : n/a
FIRE ZONE : n/a
OCCUPANCY : Assembly (Class C)
FIRE ORIGIN LOCATION : n/a
BUILDING CONSTRUCTION : Steel & Concrete
EXTENT WHEN DISCOVERED : Electrical outlet fused to two plugs
EXTENT WHEN EXTINGUISHED : n/a
CAUSE OF FIRE : Electrical failure
WHAT BURNED : Electrical outlet fused to two plugs
ESTIMATED PROPERTY LOSS : approx \$500 (if Hayworth Panel needs replacing)
DAMAGE TO : Electrical outlet and light cords
COMMAND POST LOCATION : n/a
STAGING AREA : n/a
LIST AGENCIES NOTIFIED : Cal Fire requested on bridge line, but cancelled immediately

RESPONDERS AT SCENE

FIRE OFFICERS: Stocks, Penner, Depew, Porte, Wimberly
SAFETY PERSONNEL: Joe Higgins
MEDICAL PERSONNEL: n/a
BRIGADE MEMBERS: Ops responder Breck Thomas
OPERATIONS: Shift Manager Ted Schwartzbaugh
SECURITY: n/a
OFFSITE FIRE: n/a
OFFSITE AMBULANCE: n/a
OTHER (SPECIFY): n/a

ICS POSITIONS

INCIDENT COMMANDER : Initially Eric Carter on the bridge but was cancelled
SAFETY OFFICER :
SECURITY LIAISON :
OPERATIONS CHIEF :
LOGISTICS CHIEF :
PLANNING CHIEF :

STAGING OFFICER :
MEDICAL LEADER :
OTHER (Specify) :

INCIDENT REPORTING

REPORTING PARTY :

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify:

WITNESS(ES)

Name and Title : unknown

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

none

LIST FIRE FIGHTING EQUIPMENT USED

Thermal Imaging Camera (TIC)

NARRATIVE

Responded to smoke on the 4th floor Admin Building. Fire Captain (Stocks) was on the 4th floor at the time of call and was on-scene immediately. He reported no fire, just smoke coming from a Hayworth Panel from an electrical outlet. He cancelled 9799, but requested a couple firefighters come in to assist with investigation. Control Room updated and Cal Fire was cancelled. No detectors were activated. It appears two "Hayworth" style lights were plugged into a Hayworth outlet and they had become fused together by an electrical issue. Thermal Imaging Camera (TIC) was used to search for any further hot spots on Hayworth Panels. None found. Joe Higgins was also on scene and called out a Building Mechanic for further evaluation. Two Firefighters stood by until Mechanic arrived. Wrote a/r A0720207 for fire response. Contact Captain Stocks or Firefighter Penner for further details.

A0720207

NAME : Eric Carter DATE : 2/20/08 SIGNATURE: _____

REVIEWED BY : _____ DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : Crane Bay (S/W of roll up door 130 outside)

INCIDENT # : 08-038

DATE : 3-11-2008

DISPATCHED : 1400

ON SCENE: 1405

EXTINGUISHED : 1408

AVAILABLE : 1410

TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER Specify: Smoldering butt can

INCIDENT DATA

FIRE AREA :

FIRE ZONE :

OCCUPANCY : N/A

FIRE ORIGIN LOCATION : Inside butt can

BUILDING CONSTRUCTION : N/A

EXTENT WHEN DISCOVERED : 1400

EXTENT WHEN EXTINGUISHED : 1408

CAUSE OF FIRE : Inattention to butt can maintenance

WHAT BURNED : Cigarette butts

ESTIMATED PROPERTY LOSS : N/A

DAMAGE TO : N/A

COMMAND POST LOCATION : N/A

STAGING AREA : N/A

LIST AGENCIES NOTIFIED : N/A

RESPONDERS AT SCENE

FIRE OFFICERS: Randall Ward

SAFETY PERSONNEL: N/A

MEDICAL PERSONNEL: N/A

BRIGADE MEMBERS: Ivan Winberly

OPERATIONS: N/A

SECURITY: N/A

OFFSITE FIRE: N/A

OFFSITE AMBULANCE: N/A

OTHER (SPECIFY):

ICS POSITIONS

INCIDENT COMMANDER : N/A

SAFETY OFFICER :

SECURITY LIAISON :

OPERATIONS CHIEF :

LOGISTICS CHIEF :

PLANNING CHIEF :

STAGING OFFICER :
MEDICAL LEADER :
OTHER (Specify) :

INCIDENT REPORTING

REPORTING PARTY : Control Room

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify:

WITNESS(ES)

Name and Title : Unknown

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

None

LIST FIRE FIGHTING EQUIPMENT USED

5 gal water jug

NARRATIVE

Fire Department was notified by Ops via phone of a smoldering butt can outside the Crane Bay rool up Door130 to the South West (smoking area). Firefighters (FF) Wimberly and Ward responded. In route to the incident FF Ward noticed a second butt can smoldering (west of the n/w corner of the Admin building). Upon arrival the U1 Polisher Watch had extinguished the butt can by Door130. FFs Wimberly and Ward proceeded south to extinguish the butt can by the Admin building. Available 1410 hrs.

NAME :

DATE :

SIGNATURE: _____

REVIEWED BY : _____

DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : Unit 2 Buttress north entrance

INCIDENT # : 08-039

DATE : 3-13-08

DISPATCHED : 1856

ON SCENE: 1907

EXTINGUISHED : 1907

AVAILABLE : 1907

TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER Specify: Butt can smoldering

INCIDENT DATA

FIRE AREA : n/a

FIRE ZONE : n/a

OCCUPANCY : n/a

FIRE ORIGIN LOCATION : Unit 2 Buttress north entrance butt can

BUILDING CONSTRUCTION : n/a

EXTENT WHEN DISCOVERED : n/a

EXTENT WHEN EXTINGUISHED : n/a

CAUSE OF FIRE : Multiple cigarette butts

WHAT BURNED : cigarette butts

ESTIMATED PROPERTY LOSS : 0

DAMAGE TO : none

COMMAND POST LOCATION : n/a

STAGING AREA : n/a

LIST AGENCIES NOTIFIED : none

RESPONDERS AT SCENE

FIRE OFFICERS: Cappelluti, Felix, Coito

SAFETY PERSONNEL: none

MEDICAL PERSONNEL: none

BRIGADE MEMBERS: none

OPERATIONS: Wathen

SECURITY: none

OFFSITE FIRE: none

OFFSITE AMBULANCE: none

OTHER (SPECIFY): none

ICS POSITIONS

INCIDENT COMMANDER : n/a

SAFETY OFFICER : n/a

SECURITY LIAISON : n/a

OPERATIONS CHIEF : n/a

LOGISTICS CHIEF : n/a

PLANNING CHIEF : n/a

STAGING OFFICER : n/a
MEDICAL LEADER : n/a
OTHER (Specify) : n/a

INCIDENT REPORTING

REPORTING PARTY : SGT craft

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify:

779 was called and control decided not to sound the alarm

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify:

WITNESS(ES)

Name and Title : none

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

none

LIST FIRE FIGHTING EQUIPMENT USED

none

NARRATIVE

Notified via pager of smoldering butt can outside the north entrance to Unit 2 buttress. Control room responded Wathen. Upon arrival no butt cans (2) in the area were smoking. SGT craft RP indicated he dump a gallon of water to extinguish the butt can. Coito and Felix open butt can to ensure smoldering butts were extinguished. Phoned control room (1224) and released from incident. This incident in the same area as incident 08-038 two days prior.

NAME : Cappelluti

DATE : 3-13-08

SIGNATURE: _____

REVIEWED BY : _____

DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : I&C Building
INCIDENT # : 08-054
DATE : 5-6-08
DISPATCHED : 0835 ON SCENE: 0840 EXTINGUISHED : n/a
AVAILABLE : 0900

TYPE OF INCIDENT

STRUCTURE FIRE WILDLAND FIRE VEHICLE FIRE
OTHER Specify: Fire Alarm Sounding

INCIDENT DATA

FIRE AREA : n/a
FIRE ZONE : n/a
OCCUPANCY : Group B
FIRE ORIGIN LOCATION : n/a
BUILDING CONSTRUCTION : Type II
EXTENT WHEN DISCOVERED : n/a
EXTENT WHEN EXTINGUISHED : n/a
CAUSE OF FIRE : n/a
WHAT BURNED : n/a
ESTIMATED PROPERTY LOSS : n/a
DAMAGE TO : n/a
COMMAND POST LOCATION : Outside building by hydrant
STAGING AREA : n/a
LIST AGENCIES NOTIFIED : none

RESPONDERS AT SCENE

FIRE OFFICERS: Carter & Beile
SAFETY PERSONNEL: n/a
MEDICAL PERSONNEL: n/a
BRIGADE MEMBERS: n/a
OPERATIONS: Ray Katz (Ops Responded)
SECURITY: numerous
OFFSITE FIRE: n/a
OFFSITE AMBULANCE: n/a
OTHER (SPECIFY): n/a

ICS POSITIONS

INCIDENT COMMANDER : Carter
SAFETY OFFICER : Beile
SECURITY LIAISON : numerous
OPERATIONS CHIEF : n/a
LOGISTICS CHIEF : n/a
PLANNING CHIEF : n/a

STAGING OFFICER : n/a
MEDICAL LEADER : n/a
OTHER (Specify) : n/a

INCIDENT REPORTING

REPORTING PARTY : Fire Alarm Panel

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify: Fire Panel

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify: 779

WITNESS(ES)

Name and Title :

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

Fire Alarm Panel & Detector (Zone 6 Duct Detector)

LIST FIRE FIGHTING EQUIPMENT USED

none

NARRATIVE

Responded to an alarm sounding in the I&C Building. While enroute, we received radio traffic that the building is being evacuated, 2nd floor clear of all people and no signs or odors of smoke. Upon arrival, building had nothing showing and we went into investigative mode. Building was fully evacuated by our arrival. The fire alarm panel indicated the detector in "zone 6 duct detector" was in alarm. Local audible was silenced. Upon walkdown of both floors, no signs of smoke or odors present. Detector was reset and it cleared. Both fire alarm panels (main and secondary in electrical room by north stairs) returned to normal status. Cosco will be onsite tomorrow night for other testing. Recommend they check the zone 6 detector as it may be going bad. (a0729537 written by us to track repair and Joe Higgins was notified).

NAME : Eric Carter

DATE : 5-6-08

SIGNATURE: 

REVIEWED BY : _____

DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : U1 Turb 140' (East side, Supply Fan S62)

INCIDENT # : 08-059

DATE : 06/09/2008

DISPATCHED : 0839

ON SCENE: 0842

EXTINGUISHED : N/A

AVAILABLE : 0915

TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER Specify: Reported fire in a supply fan S62. 140' U1 Turb, east side.

INCIDENT DATA

FIRE AREA :

FIRE ZONE :

OCCUPANCY :

FIRE ORIGIN LOCATION : No fire

BUILDING CONSTRUCTION : Steel framed industrial

EXTENT WHEN DISCOVERED : N/A

EXTENT WHEN EXTINGUISHED : N/A

CAUSE OF FIRE : N/A

WHAT BURNED : N/A

ESTIMATED PROPERTY LOSS : N/A

DAMAGE TO : N/A

COMMAND POST LOCATION : N/A

STAGING AREA : N/A

LIST AGENCIES NOTIFIED : N/A

RESPONDERS AT SCENE

FIRE OFFICERS: C. Paris, D. Beile, M. Penner, J. Schwarz, Dan Stocks, R. Ward,
I. Wimberly

SAFETY PERSONNEL: N/A

MEDICAL PERSONNEL: N/A

BRIGADE MEMBERS: N/A

OPERATIONS: Ops Responder (Jim Ewert)

SECURITY: Security Respsponder GIL

OFFSITE FIRE: N/A

OFFSITE AMBULANCE: N/A

OTHER (SPECIFY): N/A

ICS POSITIONS

INCIDENT COMMANDER :

SAFETY OFFICER :

SECURITY LIAISON :

OPERATIONS CHIEF :

LOGISTICS CHIEF :

PLANNING CHIEF :
STAGING OFFICER :
MEDICAL LEADER :
OTHER (Specify) :

INCIDENT REPORTING

REPORTING PARTY :

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify: Fire Alarm

WITNESS(ES)

Name and Title :

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

LIST FIRE FIGHTING EQUIPMENT USED


NARRATIVE

At approximately 0839 hrs. the fire alarm sounder for a reported fire on the U1-140' Turb deck. RP (Reporting Party) reported that smoke was coming from Supply fan S62 (east side of the U1 Turb building). Upon arrival no sign of fire was reported. Investigation continued and it was discovered that the Lube Oil vapor extractor (East side, outside of the Turbine building) fumes were being drawn into the supply fan inlet. Fire personnel stood by for the restarting of the fan and the results of the investigation were confirmed. Fire personnel were released from the scene at approximately 0940 hrs.

NAME : Randall L. Ward

DATE : 06/10/08

SIGNATURE: 

REVIEWED BY : 

DATE : 6/11/08

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : Admin Building (6th Floor Computer Rm)

INCIDENT # : 08-060

DATE : 6/29/08

DISPATCHED : 0920

ON SCENE: 0922

EXTINGUISHED : 0922

AVAILABLE : 1030

TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER Specify: Alarm Sounding

INCIDENT DATA

FIRE AREA :

N/A

FIRE ZONE :

N/A

OCCUPANCY :

Assembly

FIRE ORIGIN LOCATION :

No Fire (smoking belt on floor A/C unit)

BUILDING CONSTRUCTION :

Concrete / Steel

EXTENT WHEN DISCOVERED :

smoking

EXTENT WHEN EXTINGUISHED :

n/a

CAUSE OF FIRE :

No Fire (smoking belt)

WHAT BURNED :

belt

ESTIMATED PROPERTY LOSS :

\$100.00

DAMAGE TO :

belt

COMMAND POST LOCATION :

West of Admin Building

STAGING AREA :

VIS

LIST AGENCIES NOTIFIED :

Cal Fire and Computer Services (Doug Wise)

RESPONDERS AT SCENE

FIRE OFFICERS: Carter, Beile, Porte, Cappelluti, & Coito

SAFETY PERSONNEL: N/A

MEDICAL PERSONNEL: N/A

BRIGADE MEMBERS: N/A

OPERATIONS: Breck Thomas

SECURITY: Numerous

OFFSITE FIRE: BC Beightler (on scene), E62 staged and cancelled at VIS

OFFSITE AMBULANCE: N/A

OTHER (SPECIFY): N/A

ICS POSITIONS

INCIDENT COMMANDER : Carter

SAFETY OFFICER : Carter

SECURITY LIAISON : Carter

OPERATIONS CHIEF : Beile

LOGISTICS CHIEF : N/A

PLANNING CHIEF : N/A

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : 5th Floor Admin Building

INCIDENT # : 08-065

DATE : 7-18-08

DISPATCHED : 1440 ON SCENE: 1450

EXTINGUISHED : No Fire

AVAILABLE : 1510

TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER Specify: Smoke in 5th Floor Kitchen

INCIDENT DATA

FIRE AREA : N/A

FIRE ZONE : N/A

OCCUPANCY : Assembly

FIRE ORIGIN LOCATION : No Fire

BUILDING CONSTRUCTION : Concrete & Steel

EXTENT WHEN DISCOVERED : Smoldering tin electric burner cover (burner left on)

EXTENT WHEN EXTINGUISHED : No Fire

CAUSE OF FIRE : No Fire

WHAT BURNED :

ESTIMATED PROPERTY LOSS : \$1.00

DAMAGE TO : Burner Cover

COMMAND POST LOCATION : Not established

STAGING AREA : N/A

LIST AGENCIES NOTIFIED : Cal Fire (cancelled enroute)

RESPONDERS AT SCENE

FIRE OFFICERS: Carter, Cappelluti, Coito, Porte & Felix

SAFETY PERSONNEL: N/A

MEDICAL PERSONNEL: N/A

BRIGADE MEMBERS: N/A

OPERATIONS: Ops Responder Arellano

SECURITY: Numerous

OFFSITE FIRE: N/A (cancelled enroute)

OFFSITE AMBULANCE: N/A

OTHER (SPECIFY): N/A

ICS POSITIONS

INCIDENT COMMANDER : Not established

SAFETY OFFICER : N/A

SECURITY LIAISON : N/A

OPERATIONS CHIEF : N/A

LOGISTICS CHIEF : N/A

PLANNING CHIEF : N/A

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : Admin Building (6th Floor Computer Rm)
INCIDENT # : 08-060
DATE : 6/29/08
DISPATCHED : 0920 ON SCENE: 0922 EXTINGUISHED : 0922
AVAILABLE : 1030

TYPE OF INCIDENT

STRUCTURE FIRE WILDLAND FIRE VEHICLE FIRE
OTHER Specify: Alarm Sounding

INCIDENT DATA

FIRE AREA : N/A
FIRE ZONE : N/A
OCCUPANCY : Assembly
FIRE ORIGIN LOCATION : No Fire (smoking belt on floor A/C unit)
BUILDING CONSTRUCTION : Concrete / Steel
EXTENT WHEN DISCOVERED : smoking
EXTENT WHEN EXTINGUISHED : n/a
CAUSE OF FIRE : No Fire (smoking belt)
WHAT BURNED : belt
ESTIMATED PROPERTY LOSS : \$100.00
DAMAGE TO : belt
COMMAND POST LOCATION : West of Admin Building
STAGING AREA : VIS
LIST AGENCIES NOTIFIED : Cal Fire and Computer Services (Doug Wise)

RESPONDERS AT SCENE

FIRE OFFICERS: Carter, Beile, Porte, Cappelluti, & Coito
SAFETY PERSONNEL: N/A
MEDICAL PERSONNEL: N/A
BRIGADE MEMBERS: N/A
OPERATIONS: Breck Thomas
SECURITY: Numerous
OFFSITE FIRE: BC Beightler (on scene), E62 staged and cancelled at VIS
OFFSITE AMBULANCE: N/A
OTHER (SPECIFY): N/A

ICS POSITIONS

INCIDENT COMMANDER : Carter
SAFETY OFFICER : Carter
SECURITY LIAISON : Carter
OPERATIONS CHIEF : Beile
LOGISTICS CHIEF : N/A
PLANNING CHIEF : N/A

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : 5th Floor Admin Building

INCIDENT # : 08-065

DATE : 7-18-08

DISPATCHED : 1440

ON SCENE: 1450

EXTINGUISHED : No Fire

AVAILABLE : 1510

TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER Specify: Smoke in 5th Floor Kitchen

INCIDENT DATA

FIRE AREA : N/A

FIRE ZONE : N/A

OCCUPANCY : Assembly

FIRE ORIGIN LOCATION : No Fire

BUILDING CONSTRUCTION : Concrete & Steel

EXTENT WHEN DISCOVERED : Smoldering tin electric burner cover (burner left on)

EXTENT WHEN EXTINGUISHED : No Fire

CAUSE OF FIRE : No Fire

WHAT BURNED :

ESTIMATED PROPERTY LOSS : \$1.00

DAMAGE TO : Burner Cover

COMMAND POST LOCATION : Not established

STAGING AREA : N/A

LIST AGENCIES NOTIFIED : Cal Fire (cancelled enroute)

RESPONDERS AT SCENE

FIRE OFFICERS: Carter, Cappelluti, Coito, Porte & Felix

SAFETY PERSONNEL: N/A

MEDICAL PERSONNEL: N/A

BRIGADE MEMBERS: N/A

OPERATIONS: Ops Responder Arellano

SECURITY: Numerous

OFFSITE FIRE: N/A (cancelled enroute)

OFFSITE AMBULANCE: N/A

OTHER (SPECIFY): N/A

ICS POSITIONS

INCIDENT COMMANDER : Not established

SAFETY OFFICER : N/A

SECURITY LIAISON : N/A

OPERATIONS CHIEF : N/A

LOGISTICS CHIEF : N/A

PLANNING CHIEF : N/A

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : Unit 2 Transformer Yard "C" Phase Main Bank
INCIDENT # : 08-070
DATE : 8-16-08
DISPATCHED : 2359 ON SCENE: 0005 EXTINGUISHED : 0026
AVAILABLE : 0530

TYPE OF INCIDENT

STRUCTURE FIRE WILDLAND FIRE VEHICLE FIRE
OTHER Specify: Transformer Fire

INCIDENT DATA

FIRE AREA : 29
FIRE ZONE : N/A
OCCUPANCY : N/A
FIRE ORIGIN LOCATION : Insulator on top of "C" phase
BUILDING CONSTRUCTION : N/A (Steel Cased Transformer with approx 20,000 gal of oil)
EXTENT WHEN DISCOVERED : 50 to 60 foot flame lengths
EXTENT WHEN EXTINGUISHED : Fire out
CAUSE OF FIRE : Investigation in progress by numerous disciplines at DCP
WHAT BURNED : Oil
ESTIMATED PROPERTY LOSS : To be determined by management
DAMAGE TO : "C" Phase Tx, "B" Phase Tx, Admin Bld, Turbine Bld, & Plant Air Compressor Building
COMMAND POST LOCATION : East side of Admin
STAGING AREA : Warehouse B
LIST AGENCIES NOTIFIED : Cal Fire

RESPONDERS AT SCENE

FIRE OFFICERS: Carter, Cappelluti, Porte, Coito, & Felix
SAFETY PERSONNEL: N/A
MEDICAL PERSONNEL: N/A
BRIGADE MEMBERS: Bo Allen (Ops Responder)
OPERATIONS: Dan Stermer & Jim Welsch
SECURITY: Numerous
OFFSITE FIRE: First Alarm staged at Warehouse B, B3411 responded to CP
OFFSITE AMBULANCE: N/A
OTHER (SPECIFY): N/A

ICS POSITIONS

INCIDENT COMMANDER : Carter
SAFETY OFFICER : Carter
SECURITY LIAISON : Numerous
OPERATIONS CHIEF : Carter

degree range on the transformer body and 65 degrees on the insulator tip (after extinguishment). We left one personnel on reflash watch for the rest of the shift just to be certain this did reflash again.

Fire dept wrote A/R A0738090 for plant documentation.

NAME : Eric Carter

DATE : 8-17-08

SIGNATURE: _____

REVIEWED BY : _____

DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : penthouse administration building

INCIDENT # : 08-073

DATE : 8-26-08

DISPATCHED : 0013

ON SCENE:

EXTINGUISHED :

AVAILABLE :

TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER Specify:

INCIDENT DATA

FIRE AREA :

Administration building

FIRE ZONE :

detector P115

OCCUPANCY :

office

FIRE ORIGIN LOCATION :

BUILDING CONSTRUCTION :

EXTENT WHEN DISCOVERED :

EXTENT WHEN EXTINGUISHED :

CAUSE OF FIRE :

WHAT BURNED :

ESTIMATED PROPERTY LOSS :

DAMAGE TO :

COMMAND POST LOCATION :

STAGING AREA :

LIST AGENCIES NOTIFIED :

RESPONDERS AT SCENE

FIRE OFFICERS: Stocks, Ellis, Porte, Rigby, Wimberly

SAFETY PERSONNEL:

MEDICAL PERSONNEL:

BRIGADE MEMBERS:

OPERATIONS:

SECURITY:

OFFSITE FIRE: none

OFFSITE AMBULANCE:

OTHER (SPECIFY):

ICS POSITIONS

INCIDENT COMMANDER : Stocks

SAFETY OFFICER :

SECURITY LIAISON :

OPERATIONS CHIEF :

LOGISTICS CHIEF :

PLANNING CHIEF :

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : DCPP Administration Building

INCIDENT # : 08-078

DATE : 09-12-08

DISPATCHED : 1510

ON SCENE: 1517

EXTINGUISHED : N/A

AVAILABLE : 1522

TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER Specify: Fire Alarm

INCIDENT DATA

FIRE AREA : Administration Building

FIRE ZONE : East Computer Room

OCCUPANCY :

FIRE ORIGIN LOCATION : N/A

BUILDING CONSTRUCTION :

EXTENT WHEN DISCOVERED : FAP in Alarm

EXTENT WHEN EXTINGUISHED : N/A

CAUSE OF FIRE : N/A

WHAT BURNED : N/A

ESTIMATED PROPERTY LOSS : N/A

DAMAGE TO : N/A

COMMAND POST LOCATION : 6th Floor

STAGING AREA : N/A

LIST AGENCIES NOTIFIED : N/A

RESPONDERS AT SCENE

FIRE OFFICERS: Ellis, Ward, Rigby, Wimberly, Turner

SAFETY PERSONNEL: None

MEDICAL PERSONNEL: None

BRIGADE MEMBERS: None

OPERATIONS: Ops Responder not requested

SECURITY: Various

OFFSITE FIRE: Not requested

OFFSITE AMBULANCE: N/A

OTHER (SPECIFY):

ICS POSITIONS

INCIDENT COMMANDER : Ellis

SAFETY OFFICER : Ellis

SECURITY LIAISON : Various

OPERATIONS CHIEF : Not Assigned

LOGISTICS CHIEF : Not Assigned

PLANNING CHIEF : Not Assigned

STAGING OFFICER : Not Assigned
MEDICAL LEADER : Not Assigned
OTHER (Specify) :

INCIDENT REPORTING

REPORTING PARTY : Control Room / Building Occupant

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify: Fire Computer

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify: Radio

WITNESS(ES)

Name and Title :

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

Smoke detector activated, building evacuation requested via 779 bridge line.

LIST FIRE FIGHTING EQUIPMENT USED

None

NARRATIVE

The fire department was informed via Control Room (by radio) and concurrently by building occupant (via 3027) of activation of a detector on the 6th floor, east computer room. No smoke or fire was reported; C/R asked if the fire alarm should be sounded, and due to potential Security access issues (no P.A. vehicle access through Gate 1, Gate 20 the designated route) it was determined that sounding the Fire Alarm and establishment of the bridge line as well as a P.A. announcement to evacuate the building would be prudent. E9791 responded with full crew complement through Gate 1 (as re-directed by Security) and staged west of Admin Building. A search to determine the location of the detector in alarm was initiated after verifying no fire or smoke, and silencing the building evacuation alarms (building alarm in "bypass".)

The area of the detector in question was determined to be the keycard-controlled (east) computer room. All (5) ceiling and (4) under-floor detectors were inspected - none were found in alarm, yet the panel would not clear after several attempts. After discussion with Ops SFM Coward, a decision was made to attempt to replace detectors in sequence, attempting to reset the panel each time. This effort proved to be unsuccessful. This was communicated to C/R staff, with the decision to contact Cosco for repair while leaving the building alarm in "bypass". As this was a less-than-ideal solution, a final attempt was made to reset the FAP, which was successful.

Lessons learned: The theory is that if an alarm causes the Cerberus FAP (newer panel on left) to be in an alarm condition, the older Pytronics panel cannot be reset, even if the detector has reset locally. It is necessary to reset the Cerberus panel first, THEN reset the main FAP as has historically been done. If this had been attempted earlier, swapping out detectors might not have been necessary.

NAME : Scott Ellis DATE : 09-12-08 SIGNATURE: _____

REVIEWED BY : _____ DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : Second Floor Duct Detector I&C Building

INCIDENT # : 08-079

DATE : 9-18-08

DISPATCHED : 0625

ON SCENE:

EXTINGUISHED :

AVAILABLE :

TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER Specify:

INCIDENT DATA

FIRE AREA :

I & C Building

FIRE ZONE :

Second Floor Duct Detector

OCCUPANCY :

office

FIRE ORIGIN LOCATION :

BUILDING CONSTRUCTION :

EXTENT WHEN DISCOVERED :

EXTENT WHEN EXTINGUISHED :

CAUSE OF FIRE :

WHAT BURNED :

ESTIMATED PROPERTY LOSS :

DAMAGE TO :

COMMAND POST LOCATION :

STAGING AREA :

LIST AGENCIES NOTIFIED :

RESPONDERS AT SCENE

FIRE OFFICERS: Stocks, Ellis, Turner, Rigby, Wimberly

SAFETY PERSONNEL:

MEDICAL PERSONNEL:

BRIGADE MEMBERS:

OPERATIONS: John Hurlburt

SECURITY:

OFFSITE FIRE: none

OFFSITE AMBULANCE:

OTHER (SPECIFY):

ICS POSITIONS

INCIDENT COMMANDER : Stocks

SAFETY OFFICER :

SECURITY LIAISON :

OPERATIONS CHIEF :

LOGISTICS CHIEF :

PLANNING CHIEF :

STAGING OFFICER :
MEDICAL LEADER :
OTHER (Specify) :

INCIDENT REPORTING

REPORTING PARTY :

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify: Fire Alarm

WITNESS(ES)

Name and Title :

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

Second floor duct detector. Activated both fire alarm panels in building.

LIST FIRE FIGHTING EQUIPMENT USED

none

NARRATIVE

The fire department responded to a duct detector activation on the second floor of the I&C Bldg. The bldg alarms were activated and the occupants were evacuated. The activated detector was found. There was no sign of smoke or fire. The alarm was reset. The air handler associated with the ducting was not running after the system was reset. It is not known if the air handler was running when the detector was activated. COSTCO and A J Refrigeration were notified of the situation. They were going to further investigate the cause of the alarm.

NAME : Dan Stocks

DATE : 9-18-08

SIGNATURE: 

REVIEWED BY : _____

DATE : _____

DIABLO CANYON POWER PLANT

HAZ-MAT INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : U2 12KV Switchgear room

INCIDENT # : 08-081

DATE : 09/26/08

DISPATCHED : 2241

ON SCENE: 2245

CONTAINED:

CLEANED UP:

AVAILABLE: 1300

INCIDENT DATA

MATERIAL RELEASED : CO2

REPORTABLE OR INCIDENTAL :

LOCATION OF RELEASE :

SIZE OF RELEASE :

QUANTITY OF RELEASE :

COMMAND POST LOCATION :

STAGING AREA :

DECON LOCATION :

LIST AGENCIES NOTIFIED :

RESPONDERS AT SCENE

FIRE OFFICERS: Randall Ward, Nick DePew, Mark Penner, Jeff Schwarz & Mark Turner

SAFETY PERSONNEL:

MEDICAL PERSONNEL:

BRIGADE MEMBERS:

OPERATIONS: Ops Responder

SECURITY:

ENVIRONMENTAL ENG

CHEMISTRY AND R.P. Access Sr.

OFFSITE FIRE:

OFFSITE AMBULANCE:

OTHER (SPECIFY):

ICS POSITIONS

INCIDENT COMMANDER :

SAFETY OFFICER :

SECURITY LIAISON :

OPERATIONS CHIEF :

LOGISTICS CHIEF :

PLANNING CHIEF :

STAGING OFFICER :

TECH REF :

HM GROUP SUPERVISOR :

DECON LEADER :

ENTRY LEADER :

MEDICAL LEADER :

OTHER (Specify) :

MONITORING SAMPLES

TIME :

O2 % :

LEL % :

pH :

% /PPM :

INCIDENT REPORTING

REPORTING PARTY : Ops

CONTROL ROOM NOTIFIED

No Yes x VIA: Phone x 779 Other Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes x VIA: Phone Pager x PA Other Specify: 779

WITNESS(ES)

Name and Title :

NARRATIVE

Responded to 779 a CO2 leak in the 12KV Switchgear room. Ops isolated the CO2 tank. We open the "Blast Doors" to the U2 Diesel hallway and cleared the hallway and the Switchgear room. We cleared the Turbine building, Switchgear room and the Diesel hallway, returned all doors to normal status, barricaded around the leaking hose reel station (#14) and released the incident back to Ops for repairs.

NAME : Randall Ward DATE : 09/27/08 SIGNATURE: _____

REVIEWED BY : _____ DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : U1 PPC Room

INCIDENT # : DCP#08-084 Cal Fire #8587

DATE : 11-10-08

DISPATCHED : 0933

ON SCENE: 0933

EXTINGUISHED : 0933

AVAILABLE : 1219

TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER Specify:

INCIDENT DATA

FIRE AREA : Unit 1 PPC Room
FIRE ZONE : 8A
OCCUPANCY : Unoccupied Computer Room
FIRE ORIGIN LOCATION : Transformer
BUILDING CONSTRUCTION : Cement
EXTENT WHEN DISCOVERED : Smoking
EXTENT WHEN EXTINGUISHED : Self Extinguished
CAUSE OF FIRE : Transformer failure
WHAT BURNED : Transformer internals
ESTIMATED PROPERTY LOSS : \$5000
DAMAGE TO : Transformer
COMMAND POST LOCATION : 140' Fire Brigade Locker
STAGING AREA : 140' Fire Brigade Locker
LIST AGENCIES NOTIFIED : Cal Fire

RESPONDERS AT SCENE

FIRE OFFICERS: Stocks, Cappelluti, Ellis, Turner, Wimberly, Rigby, Paris
SAFETY PERSONNEL: Juarez
MEDICAL PERSONNEL: None
BRIGADE MEMBERS: None
OPERATIONS: Trigg, Polewczak, McEntire, Katz, Pate, McDonald, Racette
SECURITY: Various
OFFSITE FIRE: Bat 3416 (Chief Rob Lewin)
OFFSITE AMBULANCE: None
OTHER (SPECIFY): None

ICS POSITIONS

INCIDENT COMMANDER : Stocks
SAFETY OFFICER : Stocks
SECURITY LIAISON : Not assigned
OPERATIONS CHIEF : Not assigned
LOGISTICS CHIEF : Not assigned
PLANNING CHIEF : Not assigned

STAGING OFFICER : Not assigned
MEDICAL LEADER : Not assigned
OTHER (Specify) : Not assigned

INCIDENT REPORTING

REPORTING PARTY :

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify: Orally

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify: Fire alarm

WITNESS(ES)

Name and Title : Jack Trigg

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

Smoke detector in room.

LIST FIRE FIGHTING EQUIPMENT USED

Thermal Imaging Camera, Hot Stick

NARRATIVE


The fire alarm was sounded for a smoking transformer in the Unit1 PPC Room. An Operator was in the room and smelt an odor of smoke. Upon further investigation he saw a transformer with smoke coming out of the top. The transformer was approximately 9 feet up off of the floor mounted to the wall. He immediately left the room and had the fire alarm activated. The fire captain on duty (Capt. Stocks) was just entering the Control Room when the alarm sounded. Chief Paris took control of the bridgeline while Capt. Stocks investigated the report. The transformer could be seen from the adjacent room by looking through the window in the door. It was indeed smoking. Personel in the Control Room were unsure what the transformer was used for or how to isolate the power to it. Capt. Ellis was the first person on scene in turnouts and a SCBA. He entered the room and got the identification number from the transformer. As he was entering the room the transformer stopped smoking. It never starting smoking again. Chief Paris requested Cal Fire to respond while he was on the bridge line. The following units were dispatched: B3416, E3485, E62R, E64R, R64, and T9141. All units were cancelled when the transformer stopped smoking. B3416 continued in to see what caused the transformer to smoke. DCPP fire personel stood by for 2.5 hours until the power to the transformer was verified off. The ventilation to the room was set to fire mode so fresh air was pushed into the room and all the air in the room was exhausted to the outside. TIC readings were taken periodically while we were standing by to verify the temperature of the transformor was either stable or decreasing. A final fire patrol was done at 1500 with the TIC. The transformer temperature was the same as the room.

SARN 50084363

NAME : Dan Stocks

DATE : 11-10-08

SIGNATURE:



REVIEWED BY : _____

DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : 85' Unit 1 Dirty lube oil room
INCIDENT # : 08-086
DATE : 11-12-08
DISPATCHED : 0115 ON SCENE: 0122 EXTINGUISHED : No Fire
AVAILABLE : 0239

TYPE OF INCIDENT

STRUCTURE FIRE WILDLAND FIRE VEHICLE FIRE
OTHER Specify: Failed electric motor

INCIDENT DATA

FIRE AREA :
FIRE ZONE :
OCCUPANCY :
FIRE ORIGIN LOCATION : 85' Unit 1 Dirty Lube Oil Room
BUILDING CONSTRUCTION : Concrete
EXTENT WHEN DISCOVERED : Smoking electric motor
EXTENT WHEN EXTINGUISHED :
CAUSE OF FIRE : Fault in Motor for Fan E-55
WHAT BURNED :
ESTIMATED PROPERTY LOSS :
DAMAGE TO : Fan Motor Only
COMMAND POST LOCATION : Outside door 129
STAGING AREA :
LIST AGENCIES NOTIFIED : Cal-Fire

RESPONDERS AT SCENE

FIRE OFFICERS: Schroeder, Ward, Depew, Penner, Schwarz
SAFETY PERSONNEL:
MEDICAL PERSONNEL:
BRIGADE MEMBERS:
OPERATIONS: Rick Hicks, Joy Scaggs
SECURITY: Blythe, Winterberg
OFFSITE FIRE:
OFFSITE AMBULANCE:
OTHER (SPECIFY):

ICS POSITIONS

INCIDENT COMMANDER : Schroeder
SAFETY OFFICER :
SECURITY LIAISON :
OPERATIONS CHIEF :
LOGISTICS CHIEF :
PLANNING CHIEF :

STAGING OFFICER :
MEDICAL LEADER :
OTHER (Specify) :

INCIDENT REPORTING

REPORTING PARTY :

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify:

WITNESS(ES)

Name and Title :

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

LIST FIRE FIGHTING EQUIPMENT USED

NARRATIVE

Responded to a report of fire in the 85' Unit 1 dirty lube oil room. Requested Cal-Fire. Delayed at VIS for approximately 3 minutes. The crash gates were down, but no security officer to wave us past. En route received information that an electric motor had tripped for Exhaust Fan E-55. Report of smoke filled room. Staged Engine 9791 outside door 129 of the Turbine Bldg. Entered lube oil room to recon. Using TIC, motor was 200 degrees upon entry. No visible fire or fire damage. Cancelled Cal-Fire response. Ventilated room. Had Security open west roll up door to crane bay to assist in ventilation. Stood by for half an hour for reflash. Motor about 100 degrees when we left.

SAP N 50084036

NAME : Schroeder DATE : 11-12-08 SIGNATURE: _____

REVIEWED BY : _____ DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : Haz Waste Building (Area 10)
INCIDENT # : 08-088
DATE : 12/9/08
DISPATCHED : 1055 ON SCENE: 1101 EXTINGUISHED : 1055
AVAILABLE : 1055

TYPE OF INCIDENT

STRUCTURE FIRE WILDLAND FIRE VEHICLE FIRE
OTHER Specify: Electrical Fire

INCIDENT DATA

FIRE AREA : n/a
FIRE ZONE : n/a
OCCUPANCY : H-7 Occupancy (hazardous storage facility)
FIRE ORIGIN LOCATION : extension cord
BUILDING CONSTRUCTION : metal
EXTENT WHEN DISCOVERED : extinguished
EXTENT WHEN EXTINGUISHED : minor char and discoloration on extension cord (female end)
and GFCI (male end)
CAUSE OF FIRE : electrical
WHAT BURNED : extension cord and GFCI
ESTIMATED PROPERTY LOSS : \$30.00
DAMAGE TO : see above
COMMAND POST LOCATION : outside haz waste building
STAGING AREA : n/a
LIST AGENCIES NOTIFIED : n/a

RESPONDERS AT SCENE

FIRE OFFICERS: Carter, Beile, Porte, Felix and Penner
SAFETY PERSONNEL: n/a
MEDICAL PERSONNEL: n/a
BRIGADE MEMBERS: n/a
OPERATIONS: n/a
SECURITY: Security liason
OFFSITE FIRE: not requested
OFFSITE AMBULANCE: not requested
OTHER (SPECIFY): n/a

ICS POSITIONS

INCIDENT COMMANDER : Carter
SAFETY OFFICER : Beile
SECURITY LIAISON :
OPERATIONS CHIEF :
LOGISTICS CHIEF :

PLANNING CHIEF :
STAGING OFFICER :
MEDICAL LEADER :
OTHER (Specify) :

INCIDENT REPORTING

REPORTING PARTY :

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify:

WITNESS(ES)

Name and Title : Marge (from Haz Waste)

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

None

LIST FIRE FIGHTING EQUIPMENT USED

TIC (Thermal Imaging Camera) for temp readings

NARRATIVE

While just finishing a quarterly fire drill in the PA, the fire alarm was sounded for a possible fire in the Haz Waste Building (outside the PA). While on the bridge, two different reporting party's stated the fire was out. Upon arrival (small delay in exiting PA), found an extension cord that was plugged into a GFCI was charred. The charring was limited to both male (GFCI) and female (cord) plug ends. There was no fire observed by the fire dept, nor was there any smoke in the building. Temperature reading of the plug ends were 130 degrees F and cooling. We unplugged the extension cord from the power source, confirmed there was nothing combustible around the cords, and turned the scene over to building services.

SAPN 50114694

NAME : Eric Carter

DATE : 12/9/08

SIGNATURE: _____

REVIEWED BY : _____

DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : Lot 1

INCIDENT # : 08-090

DATE : 12/10/08

DISPATCHED : 0615

ON SCENE: 0618

EXTINGUISHED : 0618

AVAILABLE : 0630

TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER Specify: Vehicle Fire in parking lot #1

INCIDENT DATA

FIRE AREA : N/A

FIRE ZONE : N/A

OCCUPANCY : N/A

FIRE ORIGIN LOCATION : N/A

BUILDING CONSTRUCTION : N/A

EXTENT WHEN DISCOVERED : No fire - steam coming from a bad radiator

EXTENT WHEN EXTINGUISHED : N/A

CAUSE OF FIRE : N/A

WHAT BURNED : N/A

ESTIMATED PROPERTY LOSS : N/A

DAMAGE TO : N/A

COMMAND POST LOCATION : N/A

STAGING AREA : N/A

LIST AGENCIES NOTIFIED : Environmental Operations (Trevor Rebel)

RESPONDERS AT SCENE

FIRE OFFICERS: Beile, Porte, Felix, and Penner

SAFETY PERSONNEL: N/A

MEDICAL PERSONNEL: N/A

BRIGADE MEMBERS: N/A

OPERATIONS: N/A

SECURITY: N/A

OFFSITE FIRE: N/A

OFFSITE AMBULANCE: N/A

OTHER (SPECIFY): N/A

ICS POSITIONS

INCIDENT COMMANDER : Beile

SAFETY OFFICER : Beile

SECURITY LIAISON :

OPERATIONS CHIEF :

LOGISTICS CHIEF :

PLANNING CHIEF :

STAGING OFFICER :
MEDICAL LEADER :
OTHER (Specify) :

INCIDENT REPORTING

REPORTING PARTY : Security

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify: 779

WITNESS(ES)

Name and Title :

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

N/A

LIST FIRE FIGHTING EQUIPMENT USED

Kitty Litter

NARRATIVE

Responded to a vehicle fire in Lot 1. Upon arrival, found no fire, just steam coming from a bad radiator. Steam levels were increased due to outside temp being very low. Approx a half a gallon of anti-freeze leaked onto parking lot. It was absorbed with kitty litter. Kitty litter was swept up and placed in a labled double bag and dropped off at Haz Waste (Area 10). Vehicle owner was advised to have vehicle towed off-site. Cleared scene

NAME : Eric Carter DATE : 12/10/08 SIGNATURE: _____

REVIEWED BY : _____ DATE : _____