

Incident Response Log - 2009

Response Number	Response Code(s) *	Date	Description of Response	Log Entry By:	A/R Number
09-001	F	1/2/09	Fire Alarm (Alarm) - False (Steam from cleaning)	EC	N/A
09-002	M	1-9-09	Sick Security Officer	DTS	N/A
09-003	H	1-9-09	Polaris leaking Fuel	DTS	NA
09-004	M	1-9-09	Sick TA	DTS	NA
09-005	O	1/14/09	VEHICLE vs. car @ 6.2 miles - ROAD INJURY	DASA	N/A
09-006	M	1/20/09	Unconscious male	EC	N/A
09-007	M	1/20/09	Dizzy Security Officer	EC	N/A
09-008	M	1-21	Diabetic Emergency	EC	N/A
09-009	M	1-29	Motorcycle TC 2.2 mile marker	EC	N/A
09-010	M	2-6-09	MOTORCYCLE TC 4.5	EC	N/A
09-011	H	2/6	Oil leak @ Intake	EC	50195505
09-012	M	2/7	Med Fac requesting ambulance	EC	N/A
09-013	H	2-8	DFO spill Unit 1 butness	EC	50200143
09-014	O	2-10	VEHICLE OFF ROAD @ 1.2 MILE MARKER	EC	N/A
09-015	M	2-14	Med Aid - pt feeling dizzy @ Cafeteria (0000)	EC	N/A
09-016	F	2-14	Light smoke in Medy Room - no fire (0300)	EC	50201647
09-017	M	2-16	STOMACH PAIN IN CAFETERIA	EC	
09-018	M	2-16	MED FAC REQUESTING AMBULANCE FOR GAST PAIN	EC	
09-019	M	2-17	MED FAC REQUESTING AMBULANCE FOR COLIC PAIN	EC	
09-020	M	2-19	MED AID - Unconscious @ Forearm @ intake	EC	

Incident Response Log - 2009

Response Number	Response Code(s) *	Date	Description of Response	Log Entry By:	A/R Number
09-021	F	2-20-09	Smoke at exit turnstile in Security Bldg.	P	50204084
09-022	H	2-22-09	Hazardous air intake - microscopic SILICONE	P	50204791
09-023	M	2-24-09	med Aid (slip/fall in Containment)	EC	
09-024	M	2-24-09	Medical Aide (unconscious by 115' RCA South Gate)	P	
09-025	F	2-28-09	Exhaustion cord fire on 140' Aux Bldg deck	P	50206804
09-026	M	3-1-09	Tightness in chest	JW	
09-027	M F	3-3-09	Extinguished fire in Containment	EC	50208083
09-028	M	3-8-09	Poss. allergic reaction - 140' CAF.	P	
09-029	F	3-9-09	Welding head fire (UI Containment)	EC	50210194
09-030	M	3-10-09	med Aid (back pain @ 140' Access - UI)	EC	
09-031	M	3-10-09	med Aid (foreign object in eye @ 140 Access - UI)	EC	
09-032	F	3-10-09	Smoke check NPG Warehouse - Evapor. Pan	P	50210194
09-033	M	3-18-09	BAGAL PAIN	RWJ	
09-034	M	3-19-09	SECURITY OFFICER FELL IN UNIT 2 FIBR STAIRWELL	P	
09-035	M	4-4-09	SECURITY OFFICER PRE-EXISTING BACK INJURY FROM HOME	P	N/A
09-036	H	4/6/09	SULFURIC ACID SPILL ON ACCESS ROAD 2-3 NIS	P	50230539
09-037	M	4/27/09	MOTORCYCLE ACCIDENT AT HAIRPIN TURN.	P	
09-038	M	4-25-09	MEDICAL AIDE (ILL MALE - FLU SYMPTOMS)	STC	N/A
09-039	M	5/13/09	MEDICAL AID / LIGHT HEAD	P	
09-040	M	5/29/09	MEDICAL AID / FEELING ^{ABANDONED} FUMMY FLU SYMPTOMS	JW	N/A

* Fire Medical Hazmat Rescue Other

Incident Response Log - 2009

Response Number	Response Code(s) *	Date	Description of Response	Log Entry By:	A/R Number
09-041	F	6/2/09	Fire alarm in Containment	EC	502-13611
09-042	F	6/3/09	Activation Smoke alarm Admin Building 3rd Floor	DTS	50244123
09-043	M	6/17/09	Medical Aid Possible Seizure	MP	N/A
09-044	M	6/20/09	TWISTED ANGLE - MINOR - WALK INTO MED FACILITY	EC	N/A
09-045	M	6/30/09	400V shock to pt (UI 480V BUS G. 100' H Area)	EC	50252366
09-046					
09-047					
09-048					
09-049					
09-050					
09-051					
09-052					
09-053					
09-054					
09-055					
09-056					
09-057					
09-058					
09-059					
09-060					

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : 6th Floor Admin
INCIDENT # : 09-001
DATE : 1/2/09
DISPATCHED : 1735 ON SCENE: 1738
AVAILABLE : 1750

EXTINGUISHED : n/a

TYPE OF INCIDENT

STRUCTURE FIRE WILDLAND FIRE
OTHER Specify: Alarm Sounding

VEHICLE FIRE

INCIDENT DATA

FIRE AREA :
FIRE ZONE :
OCCUPANCY :
FIRE ORIGIN LOCATION :
BUILDING CONSTRUCTION :
EXTENT WHEN DISCOVERED :
EXTENT WHEN EXTINGUISHED :
CAUSE OF FIRE :
WHAT BURNED :
ESTIMATED PROPERTY LOSS :
DAMAGE TO :
COMMAND POST LOCATION :
STAGING AREA :
LIST AGENCIES NOTIFIED :

RESPONDERS AT SCENE

FIRE OFFICERS: Carter, Coito
SAFETY PERSONNEL:
MEDICAL PERSONNEL:
BRIGADE MEMBERS: Arrellano
OPERATIONS:
SECURITY: Numerous
OFFSITE FIRE:
OFFSITE AMBULANCE:
OTHER (SPECIFY):

ICS POSITIONS

INCIDENT COMMANDER : not established
SAFETY OFFICER :
SECURITY LIAISON :
OPERATIONS CHIEF :
LOGISTICS CHIEF :
PLANNING CHIEF :

STAGING OFFICER :
MEDICAL LEADER :
OTHER (Specify) :

INCIDENT REPORTING

REPORTING PARTY :

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify: Alarm Panel

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify: 779

WITNESS(ES)

Name and Title :

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

Fire Alarm System

LIST FIRE FIGHTING EQUIPMENT USED

None

NARRATIVE

Responded to a fire alarm in the 6th floor Admin (womens restroom). Upon arrival, found that a janitor was cleaning the floor with hot water, thus increasing humidity in small room, causing the dectector to activate. Detector removed, air'ed out, and re-installed. Approx 5 minutes later, the detector alarmed again. Removed the detector and placed a fan in the room to aid in humidity removal. Also replaced detector with a new one. Panel reset - cleared scene. Advised janitor to cover detectors while cleaning with hot water, and to return the fan to the 6th floor computer room after about one hour. He complied.



NAME : Eric Carter DATE : 1/2/09 SIGNATURE: _____

REVIEWED BY : _____ DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : Access Road 6.2 Mile marker

INCIDENT # : 09-005

DATE : 1-12-09

DISPATCHED : 0312

ON SCENE: 0319

EXTINGUISHED :

AVAILABLE : 0335

TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER Specify: Vehicle Vs. Cow - Non Injury

INCIDENT DATA

FIRE AREA :

FIRE ZONE :

OCCUPANCY :

FIRE ORIGIN LOCATION :

BUILDING CONSTRUCTION :

EXTENT WHEN DISCOVERED :

EXTENT WHEN EXTINGUISHED :

CAUSE OF FIRE :

WHAT BURNED :

ESTIMATED PROPERTY LOSS :

DAMAGE TO :

COMMAND POST LOCATION :

STAGING AREA :

LIST AGENCIES NOTIFIED :

RESPONDERS AT SCENE

FIRE OFFICERS: Schroeder, Ward, Carter, Beile, Rigby

SAFETY PERSONNEL:

MEDICAL PERSONNEL:

BRIGADE MEMBERS:

OPERATIONS:

SECURITY: Two Officers

OFFSITE FIRE:

OFFSITE AMBULANCE:

OTHER (SPECIFY):

ICS POSITIONS

INCIDENT COMMANDER : Schroeder

SAFETY OFFICER :

SECURITY LIAISON :

OPERATIONS CHIEF :

LOGISTICS CHIEF :

PLANNING CHIEF :

STAGING OFFICER :

MEDICAL LEADER :

OTHER (Specify) :

INCIDENT REPORTING

REPORTING PARTY : Unknown

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify:

WITNESS(ES)

Name and Title :

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

LIST FIRE FIGHTING EQUIPMENT USED

NARRATIVE

Dispatched to vehicle vs cow at 6.2 mile marker. Incoming truck struck cow at appx 35 - 40 mph. Damaged entire front of truck. Radiator and transmission cooler compromised. Truck pulled off the road. Cow was on the median. Patient examined. Negative head, neck, back, or shoulder pain. Patient did not want any treatment. Cow was drug off the road with a utility rope. Both lanes of traffic restored.

SARN 50176025

NAME : Dave Schroeder DATE : 1-12-09 SIGNATURE: _____

REVIEWED BY : _____ DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : 4.5 mile marker

INCIDENT # : 09-010

DATE : 2-4-09

DISPATCHED : 1936

ON SCENE:

EXTINGUISHED :

AVAILABLE : 2100

TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER Specify: Single vehicle TC

INCIDENT DATA

FIRE AREA :

FIRE ZONE :

OCCUPANCY :

FIRE ORIGIN LOCATION :

BUILDING CONSTRUCTION :

EXTENT WHEN DISCOVERED :

EXTENT WHEN EXTINGUISHED :

CAUSE OF FIRE :

WHAT BURNED :

ESTIMATED PROPERTY LOSS :

DAMAGE TO :

COMMAND POST LOCATION :

STAGING AREA :

LIST AGENCIES NOTIFIED :

RESPONDERS AT SCENE

FIRE OFFICERS: Schroeder, Ward, Depew, Schwarz, Penner, Wimberly

SAFETY PERSONNEL:

MEDICAL PERSONNEL:

BRIGADE MEMBERS:

OPERATIONS:

SECURITY:

OFFSITE FIRE:

OFFSITE AMBULANCE:

OTHER (SPECIFY):

ICS POSITIONS

INCIDENT COMMANDER : Schroeder

SAFETY OFFICER :

SECURITY LIAISON :

OPERATIONS CHIEF :

LOGISTICS CHIEF :

PLANNING CHIEF :

STAGING OFFICER :
MEDICAL LEADER : Penner
OTHER (Specify) :

INCIDENT REPORTING

REPORTING PARTY : Walk In to Station

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify: Walk In

WITNESS(ES)

Name and Title : Todd Bickell

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

LIST FIRE FIGHTING EQUIPMENT USED

NARRATIVE

Reporting party walked in to Station 97 to report a motorcycle down. FF Turner called 779. Responded with 9791 and 9769. Upon arrival, saw one motorcycle on its side at the 4.5 mile marker. The fence was damaged and there was no sign of a patient. Requested Cal-Fire and SLO Ambulance. Security did not respond for traffic control. Bystanders on scene reported that the patient was about ten feet down the hill in a ditch. Motorcycle was headed outbound. Patient had moderate to severe injuries. Helmet was off before we arrived. Patient was extricated from ditch and placed on backboard with full spinal precautions. Simple haul system utilized to get patient up to road. Patient loaded into ambulance and taken to Sierra Vista. 9791 stayed on scene to assist CHP with their investigation. Tow company hauled motorcycle away. Scene secured. 9791 returned to quarters at 2100 hrs.

SABN 50199046

NAME : Dave Schroeder DATE : 02-04-09 SIGNATURE: _____

REVIEWED BY : _____ DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : 1.2 Mile Marker

INCIDENT # : 09-014

DATE : 02-10-09

DISPATCHED : 1649

ON SCENE:

EXTINGUISHED :

AVAILABLE : 1750

TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER Specify: Single Vehicle TC

INCIDENT DATA

FIRE AREA :

FIRE ZONE :

OCCUPANCY :

FIRE ORIGIN LOCATION :

BUILDING CONSTRUCTION :

EXTENT WHEN DISCOVERED :

EXTENT WHEN EXTINGUISHED :

CAUSE OF FIRE :

WHAT BURNED :

ESTIMATED PROPERTY LOSS :

DAMAGE TO :

COMMAND POST LOCATION :

STAGING AREA :

LIST AGENCIES NOTIFIED :

RESPONDERS AT SCENE

FIRE OFFICERS: Randall Ward, Cameron Rigby, Jeff Schwarz

SAFETY PERSONNEL:

MEDICAL PERSONNEL:

BRIGADE MEMBERS:

OPERATIONS:

SECURITY:

OFFSITE FIRE:

OFFSITE AMBULANCE:

OTHER (SPECIFY):

ICS POSITIONS

INCIDENT COMMANDER : Randall

SAFETY OFFICER :

SECURITY LIAISON :

OPERATIONS CHIEF :

LOGISTICS CHIEF :

PLANNING CHIEF :

STAGING OFFICER :

MEDICAL LEADER : Cameron Rigby
OTHER (Specify) :

INCIDENT REPORTING

REPORTING PARTY :

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify:

WITNESS(ES)

Name and Title :

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

LIST FIRE FIGHTING EQUIPMENT USED

NARRATIVE

The Fire alarm sounded at 1649 hrs. Engine 9791 responded to the 1.2 mile marker, where I saw one vehicle off the road about 100 feet down the embankment still upright. The driver of the vehicle had self extricated and was standing up on the road. Cancelled the Cal Fire engine and reduced the ambulance to code two. Security arrived and assumed traffic control. San Luis Ambulance arrived on scene and assessed and released the driver. CHP arrived on scene to perform the investigation. Turned over the scene to Diablo Security and CHP and terminated Command. Engine 9791 returned to quarters at 1805 hrs.

NAME : Randall Ward DATE : 02-10-09 SIGNATURE: _____

REVIEWED BY : _____ DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : Ops Ready Room
INCIDENT # : 09-016
DATE : 2/14/09
DISPATCHED : 0300 ON SCENE: 0302 EXTINGUISHED : n/a
AVAILABLE : 0302

TYPE OF INCIDENT

STRUCTURE FIRE WILDLAND FIRE VEHICLE FIRE
OTHER Specify: Smoke Investigation

INCIDENT DATA

FIRE AREA :
FIRE ZONE : 25
OCCUPANCY : Shop
FIRE ORIGIN LOCATION : n/a
BUILDING CONSTRUCTION : Concrete & Steel
EXTENT WHEN DISCOVERED : light smoke in Ready Room
EXTENT WHEN EXTINGUISHED : not extinguished (no fire)
CAUSE OF FIRE : no fire (possibly dust on heater element)
WHAT BURNED : nothing
ESTIMATED PROPERTY LOSS : none
DAMAGE TO : nothing
COMMAND POST LOCATION : not established
STAGING AREA : not established
LIST AGENCIES NOTIFIED : none

RESPONDERS AT SCENE

FIRE OFFICERS: Turner, Coito
SAFETY PERSONNEL: none
MEDICAL PERSONNEL: n/a
BRIGADE MEMBERS: Jack Trygg (Ops Responded)
OPERATIONS: Ken Johnston
SECURITY: numerous
OFFSITE FIRE: n/a
OFFSITE AMBULANCE: n/a
OTHER (SPECIFY): n/a

ICS POSITIONS

INCIDENT COMMANDER : not established
SAFETY OFFICER : n/a
SECURITY LIAISON : numerous
OPERATIONS CHIEF : n/a
LOGISTICS CHIEF : n/a
PLANNING CHIEF : n/a

STAGING OFFICER : n/a
MEDICAL LEADER : n/a
OTHER (Specify) : n/a

INCIDENT REPORTING

REPORTING PARTY : Operations (unknown name)

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify: 779

WITNESS(ES)

Name and Title : Operator (unknown name)

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

none

LIST FIRE FIGHTING EQUIPMENT USED

none

NARRATIVE

Responded to a report of smoke in the Ops Ready Room. Upon arrival, found light haze through-out the room. Immediately checked the area for possible cause (ventilation system and adjacent rooms - storeroom, bathrooms, locker rooms and kitchen). Nothing found. After discussing this with a operator in the room prior to our arrival, he stated he turned on the heater. The heater had not been activated in some time. Possible cause was dust on the heating element, causing the light smoky haze and smoke odor. The smoky haze dispersed over time on its own. Natural ventilation to the room evacuated the smoky haze. Advised Operations to check the room every hour just as a precaution. No further action required, nor were we contacted by Ops later in the shift. Ops did state once the smoky haze cleared, it never returned.

SAPN 50201653

NAME : Eric Carter (for Mark Turner & Scott Coito) DATE : 2/14/09 SIGNATURE: _____

REVIEWED BY : _____ DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : Security Building

INCIDENT # : 09-021

DATE : 2-20-09

DISPATCHED : 1846 ON SCENE: 1852

AVAILABLE : 1905

EXTINGUISHED : n/a

TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER Specify: Smoking exit turnstile.

INCIDENT DATA

FIRE AREA :

FIRE ZONE :

OCCUPANCY :

FIRE ORIGIN LOCATION :

BUILDING CONSTRUCTION :

EXTENT WHEN DISCOVERED :

EXTENT WHEN EXTINGUISHED :

CAUSE OF FIRE :

Shorted electrical coil

WHAT BURNED :

Electrical coil

ESTIMATED PROPERTY LOSS :

DAMAGE TO :

East most exit turnstile

COMMAND POST LOCATION :

STAGING AREA :

LIST AGENCIES NOTIFIED :

RESPONDERS AT SCENE

FIRE OFFICERS: Cappelluti, Frazier, Beile, Wimberly, Rigby, Felix

SAFETY PERSONNEL: Beymer

MEDICAL PERSONNEL: n/a

BRIGADE MEMBERS: n/a

OPERATIONS: Kline (OPS Responder)

SECURITY: Multiple

OFFSITE FIRE: n/a

OFFSITE AMBULANCE: n/a

OTHER (SPECIFY):

ICS POSITIONS

INCIDENT COMMANDER : Cappelluti

SAFETY OFFICER :

SECURITY LIAISON :

OPERATIONS CHIEF :

LOGISTICS CHIEF :

PLANNING CHIEF :

STAGING OFFICER :

MEDICAL LEADER :

OTHER (Specify) :

INCIDENT REPORTING

REPORTING PARTY : Paris

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify: Radio

WITNESS(ES)

Name and Title : Fire Chief Chris Paris

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

None

LIST FIRE FIGHTING EQUIPMENT USED

None

NARRATIVE

Received radio traffic from Chief Paris (RP) of smoke in the Security Building exit turnstile area followed by 779 alarm. RP stated smoke in area with no flame. E9791 responded and staged inside PA west of Admin Bldg. Turnstile was de-energized by I&C Techs at scene working on faulty turnstile (50204084). Cleared smoke smell in area by natural ventilation.

NAME : Cappelluti

DATE : 9-20-09

SIGNATURE: _____

REVIEWED BY : _____

DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : 140' Aux Bldg deck by Unit 1 containment equipment hatch

INCIDENT # : 09-025

DATE : 2-28-09

DISPATCHED : 0509

ON SCENE: 0515

EXTINGUISHED : 0515

AVAILABLE : 0525

TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER Specify: Electrical fire

INCIDENT DATA

FIRE AREA : 34

FIRE ZONE : 34

OCCUPANCY :

FIRE ORIGIN LOCATION : Inside rigging storage room east on Unit containment equipment hatch.

BUILDING CONSTRUCTION : scaffold and fire retardant herculite

EXTENT WHEN DISCOVERED :

EXTENT WHEN EXTINGUISHED :

CAUSE OF FIRE : electrical short

WHAT BURNED : electrical cord connection and fire retardant herculite

ESTIMATED PROPERTY LOSS :

DAMAGE TO :

COMMAND POST LOCATION :

STAGING AREA :

LIST AGENCIES NOTIFIED :

RESPONDERS AT SCENE

FIRE OFFICERS: Cappelluti, Coito, Wimberly, Felix, Rigby, Turner, Porte

SAFETY PERSONNEL: na

MEDICAL PERSONNEL: na

BRIGADE MEMBERS: na

OPERATIONS: Trygg

SECURITY: Multiple

OFFSITE FIRE: Cancelled enroute

OFFSITE AMBULANCE: na

OTHER (SPECIFY):

ICS POSITIONS

INCIDENT COMMANDER : Cappelluti

SAFETY OFFICER :

SECURITY LIAISON :

OPERATIONS CHIEF :

LOGISTICS CHIEF :

PLANNING CHIEF :
STAGING OFFICER :
MEDICAL LEADER :
OTHER (Specify) :

INCIDENT REPORTING

REPORTING PARTY : Unknown

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify:

WITNESS(ES)

Name and Title :

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

none

LIST FIRE FIGHTING EQUIPMENT USED

20 lb MPDC fire extinguisher

NARRATIVE

Responded in E9791 to a reported fire on 140' Aux Bldg by Unit 1 containment equipment hatch. Cal Fire was requested. Porte and Turner arrived on scene and reported fire is out and was extinguished by Security officer Rocha using a MPDC extinguisher. Cal Fire was cancelled. Fire caused by electrical short at connection of 480V extension cord to a heater unit. Connection failed causing fire retardant herculite to ignite. Heater is a 480V yellow wheeled unit being used for personal comfort.

SAPN 50207669

NAME : Cappelluti

DATE : 2-28-09

SIGNATURE: _____

REVIEWED BY : _____

DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : Unit 1 Containment

INCIDENT # : 09-027

DATE : 3/4/09

DISPATCHED : 0440

AVAILABLE : 0440

ON SCENE: 0444

EXTINGUISHED : 0440

TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER Specify: Shop Vac Fire

INCIDENT DATA

FIRE AREA :

FIRE ZONE : 1-C

OCCUPANCY :

FIRE ORIGIN LOCATION : Steam Gen 1-3 Doghouse

BUILDING CONSTRUCTION : Concrete and Steel

EXTENT WHEN DISCOVERED : 1 foot flames

EXTENT WHEN EXTINGUISHED : Extinguished with "fireatch" cardox extinguisher

CAUSE OF FIRE : vacuuming hot material

WHAT BURNED : shop vac

ESTIMATED PROPERTY LOSS : \$100.00

DAMAGE TO : Shop Vac

COMMAND POST LOCATION : not established

STAGING AREA : n/a

LIST AGENCIES NOTIFIED : n/a

RESPONDERS AT SCENE

FIRE OFFICERS: Porte

SAFETY PERSONNEL:

MEDICAL PERSONNEL:

BRIGADE MEMBERS:

OPERATIONS:

SECURITY:

OFFSITE FIRE:

OFFSITE AMBULANCE:

OTHER (SPECIFY):

ICS POSITIONS

INCIDENT COMMANDER : not established

SAFETY OFFICER :

SECURITY LIAISON :

OPERATIONS CHIEF :

LOGISTICS CHIEF :

PLANNING CHIEF :

STAGING OFFICER :
MEDICAL LEADER :
OTHER (Specify) :

INCIDENT REPORTING

REPORTING PARTY : Firewatch
CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify: 779

WITNESS(ES)

Name and Title : none

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

none

LIST FIRE FIGHTING EQUIPMENT USED

5 lb "firewatch" cardox extinguisher

NARRATIVE

The fire alarm was sounded at 0440 for a fire in Unit 1 Containment that has been extinguished. Upon arrival, found a vacuum cleaner that burned in the S/G 1-3 doghouse. A firewatch on another job smelled burning plastic, located the fire, and extinguished it with a small "firewatch" cardox extinguisher. No EALs entered as fire was reported as extinguished and confirmed by Fire Dept within 15 minutes. The vacuum was had burned/melted from the bottom and the electrical cord and top of vacuum were intake. This indicated hot slag was vacuumed at some time, smoldered to build up enough heat, then ignited. Interviewing people in the area proved that nobody could pinpoint when the last hot job took place in the area. The vacuum was placed in a metal drum and is being held by the Decon Group. Numerous pictures were taken. Notification 50208083 written.

NAME : Eric Carter

DATE : 3-4-09

SIGNATURE: _____

REVIEWED BY : _____

DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : 140' Aux Bldg deck by Unit 1 containment equipment hatch

INCIDENT # : 09-025

DATE : 2-28-09

DISPATCHED : 0509

ON SCENE: 0515

EXTINGUISHED : 0515

AVAILABLE : 0525

TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER Specify: Electrical fire

INCIDENT DATA

FIRE AREA : 34

FIRE ZONE : 34

OCCUPANCY :

FIRE ORIGIN LOCATION : Inside rigging storage room east on Unit containment equipment hatch.

BUILDING CONSTRUCTION : scaffold and fire retardant herculite

EXTENT WHEN DISCOVERED :

EXTENT WHEN EXTINGUISHED :

CAUSE OF FIRE : electrical short

WHAT BURNED : electrical cord connection and fire retardant herculite

ESTIMATED PROPERTY LOSS :

DAMAGE TO :

COMMAND POST LOCATION :

STAGING AREA :

LIST AGENCIES NOTIFIED :

RESPONDERS AT SCENE

FIRE OFFICERS: Cappelluti, Coito, Wimberly, Felix, Rigby, Turner, Porte

SAFETY PERSONNEL: na

MEDICAL PERSONNEL: na

BRIGADE MEMBERS: na

OPERATIONS: Trygg

SECURITY: Multiple

OFFSITE FIRE: Cancelled enroute

OFFSITE AMBULANCE: na

OTHER (SPECIFY):

ICS POSITIONS

INCIDENT COMMANDER : Cappelluti

SAFETY OFFICER :

SECURITY LIAISON :

OPERATIONS CHIEF :

LOGISTICS CHIEF :

PLANNING CHIEF :
STAGING OFFICER :
MEDICAL LEADER :
OTHER (Specify) :

INCIDENT REPORTING

REPORTING PARTY : Unknown

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify:

WITNESS(ES)

Name and Title :

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

none

LIST FIRE FIGHTING EQUIPMENT USED

20 lb MPDC fire extinguisher

NARRATIVE

Responded in E9791 to a reported fire on 140' Aux Bldg by Unit 1 containment equipment hatch. Cal Fire was requested. Porte and Turner arrived on scene and reported fire is out and was extinguished by Security officer Rocha using a MPDC extinguisher. Cal Fire was cancelled. Fire caused by electrical short at connection of 480V extension cord to a heater unit. Connection failed causing fire retardant herculite to ignite. Heater is a 480V yellow wheeled unit being used for personal comfort.

SAPN: 50206804 → DA= 50207669

NAME : Cappelluti

DATE : 2-28-09

SIGNATURE: _____

REVIEWED BY : _____

DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : Unit 1 Containment

INCIDENT # : 09-027

DATE : 3/4/09

DISPATCHED : 0440

ON SCENE: 0444

EXTINGUISHED : 0440

AVAILABLE : 0440

TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER Specify: Shop Vac Fire

INCIDENT DATA

FIRE AREA :

FIRE ZONE : 1-C

OCCUPANCY :

FIRE ORIGIN LOCATION : Steam Gen 1-3 Doghouse

BUILDING CONSTRUCTION : Concrete and Steel

EXTENT WHEN DISCOVERED : 1 foot flames

EXTENT WHEN EXTINGUISHED : Extinguished with "fireatch" cardox extinguisher

CAUSE OF FIRE : vacuuming hot material

WHAT BURNED : shop vac

ESTIMATED PROPERTY LOSS : \$100.00

DAMAGE TO : Shop Vac

COMMAND POST LOCATION : not established

STAGING AREA : n/a

LIST AGENCIES NOTIFIED : n/a

RESPONDERS AT SCENE

FIRE OFFICERS: Porte

SAFETY PERSONNEL:

MEDICAL PERSONNEL:

BRIGADE MEMBERS:

OPERATIONS:

SECURITY:

OFFSITE FIRE:

OFFSITE AMBULANCE:

OTHER (SPECIFY):

ICS POSITIONS

INCIDENT COMMANDER : not established

SAFETY OFFICER :

SECURITY LIAISON :

OPERATIONS CHIEF :

LOGISTICS CHIEF :

PLANNING CHIEF :

STAGING OFFICER :
MEDICAL LEADER :
OTHER (Specify) :

INCIDENT REPORTING

REPORTING PARTY : Firewatch
CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify: 779

WITNESS(ES)

Name and Title : none

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

none

LIST FIRE FIGHTING EQUIPMENT USED

5 lb "firewatch" cardox extinguisher

NARRATIVE

The fire alarm was sounded at 0440 for a fire in Unit 1 Containment that has been extinguished. Upon arrival, found a vacuum cleaner that burned in the S/G 1-3 doghouse. A firewatch on another job smelled burning plastic, located the fire, and extinguished it with a small "firewatch" cardox extinguisher. No EALs entered as fire was reported as extinguished and confirmed by Fire Dept within 15 minutes. The vacuum was had burned/melted from the bottom and the electrical cord and top of vacuum were intake. This indicated hot slag was vacuumed at some time, smoldered to build up enough heat, then ignited. Interviewing people in the area proved that nobody could pinpoint when the last hot job took place in the area. The vacuum was placed in a metal drum and is being held by the Decon Group. Numerous pictures were taken. Notification 50208083 written. DA - 50208785

NAME : Eric Carter

DATE : 3-4-09

SIGNATURE: _____

REVIEWED BY : _____

DATE : _____

DIABLO CANYON POWER PLANT

FIRE INCIDENT REPORT

INDUSTRIAL FIRE OFFICER

INCIDENT LOCATION : Unit 1 Containment

INCIDENT # : 09-029

DATE : 3-9-09

DISPATCHED : 0733

ON SCENE: 0740

EXTINGUISHED : 0735

AVAILABLE : 0815

TYPE OF INCIDENT

STRUCTURE FIRE

WILDLAND FIRE

VEHICLE FIRE

OTHER Specify: Welding lead in Containment

INCIDENT DATA

FIRE AREA :

FIRE ZONE :

1-B

OCCUPANCY :

FIRE ORIGIN LOCATION :

Welding Lead

BUILDING CONSTRUCTION :

Concrete & Steel

EXTENT WHEN DISCOVERED :

small charing / flame on welding lead (approx 1 inch of lead)

EXTENT WHEN EXTINGUISHED :

extinguished

CAUSE OF FIRE :

possible metal hook on saftery lanyard came in contact with lead attachment point on welder

WHAT BURNED :

welding lead

ESTIMATED PROPERTY LOSS :

\$100.00

DAMAGE TO :

welding lead and safety lanyard

COMMAND POST LOCATION :

Outside Crane Bay roll up door

STAGING AREA :

Warehouse B

LIST AGENCIES NOTIFIED :

Cal Fire

RESPONDERS AT SCENE

FIRE OFFICERS: Paris, Carter, Beile, Stocks, Cappelluti, Ellis, Ward, Coito, & Depew

SAFETY PERSONNEL: Beymer (at Access)

MEDICAL PERSONNEL: N/A

BRIGADE MEMBERS: Ops Responder

OPERATIONS: N/A

SECURITY: Numerous

OFFSITE FIRE: Cancelled enroute

OFFSITE AMBULANCE: N/A

OTHER (SPECIFY): N/A

ICS POSITIONS

INCIDENT COMMANDER : Carter

SAFETY OFFICER : Beile

SECURITY LIAISON : Carter

OPERATIONS CHIEF : Beile

LOGISTICS CHIEF :
PLANNING CHIEF :
STAGING OFFICER :
MEDICAL LEADER :
OTHER (Specify) :

INCIDENT REPORTING

REPORTING PARTY : Lori Minton (FME)

CONTROL ROOM NOTIFIED

No Yes VIA: Phone 779 Other Specify:

INDUSTRIAL FIRE OFFICER NOTIFIED :

No Yes VIA: Phone Pager PA Other Specify: 779

WITNESS(ES)

Name and Title : Brian McQuade (Containment Coordinator)

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED

None

LIST FIRE FIGHTING EQUIPMENT USED

5 lb "firewatch" cardox extinguisher

NARRATIVE

Responded to a report of a "glowing red" electrical lead behind RCP 1-4 on the 117' in Unit 1 Containment. While enroute, the Containment Coordinator stated on Ops Repeater that a small fire was found on a portable welder electrical lead and the fire was extinguished. No EALs entered as fire was extinguished within 15 minutes. Upon arrival, found burned insulation on a welding lead and charring on a safety lanyard that was used to secure the welding lead to the welder. Possible cause was the metal clip on the lanyard came in contact with the welding lead connection point on the welder, causing excessive heat to burn the insulation. An FME worker walking by saw the glowing red lead and reported it to a Containment Coordinator. The CC responded with a small 5 lb cardox extinguisher and the FME worker dialed 779. Fire was confirmed extinguished and the welder was confirmed de-energized by the Fire Dept. Cal Fire was cancelled. Fire Dept cleared scene. Notification 50210194 written. OA → 50210187

NAME : Eric Carter

DATE : 3-9-09

SIGNATURE: _____

REVIEWED BY : _____

DATE : _____



Diablo Canyon Fire Department Fire Incident Report

INCIDENT NO. 09-029	DATE: 3/9/09	INCIDENT TIMELINE	
LOCATION: Unit 1 Containment (by RCP 1-4)		NOTIFICATION: 0733 HRS.	
UNIT: 1 <input checked="" type="checkbox"/> 2 <input type="checkbox"/> COMMON <input type="checkbox"/>		AT SCENE: 0740 HRS.	
NON-PB <input type="checkbox"/> OUTSIDE PA <input type="checkbox"/>		EXTINGUISHED: 0735 HRS.	
		AVAILABLE: 0800 HRS.	
		REFLASH WATCH? N <input checked="" type="checkbox"/> Y <input type="checkbox"/>	TIME: HRS.
		REFLASH WATCH TERMINATED:	HRS.
INCIDENT TYPE: <input type="checkbox"/> STRUCTURE <input type="checkbox"/> WILDLAND <input type="checkbox"/> VEHICLE <input type="checkbox"/> SMOKE REPORT			
<input checked="" type="checkbox"/> OTHER (specify) Small fire on a welding lead			

INCIDENT DATA			
FIRE AREA/ZONE: 1-B	OCCUPANCY:	ORIGIN: Welding Lead	
CAUSE OF FIRE: Possible metal clip on a safety lanyard came in contact with weld machine		WHAT BURNED: Welding lead and safety lanyard	
ESTIMATED PROPERTY LOSS: \$100.00		DAMAGE TO: Welding lead and lanyard	
COMMAND POST LOCATION: By Med Fac		STAGING AREA LOC.: Warehouse B	
AGENCIES NOTIFIED: Cal Fire			

RESPONDERS AT SCENE	
FIRE PERSONNEL: CH - PARIS, Christian E. FC - CARTER, Eric J. FC - BEILE, Daniel J. FC - CAPPELLUTI, Tony M. FC - WARD, Randall L. FC - STOCKS, Daniel T. FF - COITO, Scott T. FF - DEPEW, Nicholas E. FC - ELLIS, James S.	BRIGADE MEMBERS: NONE
	OPS RESPONDER: Jack Trygg
	SAFETY PERSONNEL: PGE - BEYMER, John
OFFSITE FIRE:	SECURITY: Numerous
	MEDICAL:
	SL AMBULANCE:
OTHER (specify):	

ICS POSITIONS

FC - CARTER, Eric J.

INCIDENT COMMANDER
CDF UNIFIED COMMAND

FC - Beile
FC - Carter

SAFETY OFFICER
SECURITY LIAISON

FC - Beile			
OPERATIONS	PLANNING	LOGISTICS	MEDICAL

OTHER:	OTHER:	OTHER:	OTHER:
--------	--------	--------	--------

INCIDENT REPORTING

REPORTING PARTY: Lori Minton (FME)	EMPLOYER: PG&E TA
CONTROL ROOM NOTIFIED: 779 <input checked="" type="checkbox"/> PLANT PHONE <input type="checkbox"/> OTHER <input type="checkbox"/>	
FIRE DEPT. NOTIFIED: 779 <input checked="" type="checkbox"/> PLANT PHONE <input type="checkbox"/> OTHER <input type="checkbox"/>	
WITNESS(ES): Brian McQuade (Containment Coordinator) (Include Phone Number or LAN ID)	

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED: **N/A**

LIST FIRE FIGHTING EQUIPMENT USED: **small "firewatch" 5 lb extinguisher**

NARRATIVE: Responded to a report of a "glowing red" electrical lead behind RCP 1-4 on the 117' in Unit 1 Containment. While enroute, the Containment Coordinator stated on Ops Repeater that a small fire was found on a portable welder electrical lead and the fire was extinguished. No EALs entered as fire was extinguished within 15 minutes. Upon arrival, found burned insulation on a welding lead and charring on a safety lanyard that was used to secure the welding lead to the welder. Possible cause was the metal clip on the lanyard came in contact with the welding lead connection point on the welder, causing excessive heat to burn the insulation. An FME worker walking by saw the glowing red lead and reported it to a Containment Coordinator. The CC responded with a small 5 lb cardox extinguisher and the FME worker dialed 779. Fire was confirmed extinguished and the welder was confirmed de-energized by the Fire Dept. Cal Fire was cancelled. Fire Dept cleared scene. Notification 5020194 written.

INCIDENT DOCUMENTATION

NOTIFICATION NO.(S): 50210194 DA = 50210187
OTHER REPORTS: N/A

REPORT COMPLETED BY:

FC - CARTER, Eric J.	3/9/09		
NAME	DATE	SIGNATURE	REVIEWER/DATE



Diablo Canyon Fire Department Fire Incident Report

INCIDENT NO. 09-032	DATE: 3/10/09	INCIDENT TIMELINE	
LOCATION: NPG Warehouse Environmental storage room		NOTIFICATION: 1820 HRS.	
		AT SCENE: 1825 HRS.	
		EXTINGUISHED: 1825 HRS.	
		AVAILABLE: 1930 HRS.	
UNIT: 1 <input type="checkbox"/> 2 <input type="checkbox"/> COMMON <input type="checkbox"/>		REFLASH WATCH? N <input checked="" type="checkbox"/> Y <input type="checkbox"/>	TIME: HRS.
NON-PB <input checked="" type="checkbox"/> OUTSIDE PA <input type="checkbox"/>		REFLASH WATCH TERMINATED: HRS.	
INCIDENT TYPE: <input type="checkbox"/> STRUCTURE <input type="checkbox"/> WILDLAND <input type="checkbox"/> VEHICLE <input checked="" type="checkbox"/> SMOKE REPORT			
<input type="checkbox"/> OTHER (specify)			

INCIDENT DATA		
FIRE AREA/ZONE: N/A	OCCUPANCY:	ORIGIN:
CAUSE OF FIRE: N/A	WHAT BURNED:	
ESTIMATED PROPERTY LOSS:	DAMAGE TO:	
COMMAND POST LOCATION:	STAGING AREA LOC.:	
AGENCIES NOTIFIED:		

RESPONDERS AT SCENE	
FIRE PERSONNEL: FC - CAPPELLUTI, Tony M. FC - CARTER, Eric J. FF - FRAZIER, Daniel F. FF - PENNER, Mark J. FF - RIGBY, Cameron B. FF - WIMBERLY, Ivan G. CH - PARIS, Christian E.	BRIGADE MEMBERS:
	OPS RESPONDER: none
	SAFETY PERSONNEL:
OFFSITE FIRE: none	SECURITY:
	MEDICAL:
	SL AMBULANCE:
OTHER (specify): Brian Rodrigues (warehouse supervisor)	

ICS POSITIONS

FC - CAPPELLUTI, Tony M.

INCIDENT COMMANDER

CDF UNIFIED COMMAND

SAFETY OFFICER
SECURITY LIAISON

OPERATIONS	PLANNING	LOGISTICS	MEDICAL
------------	----------	-----------	---------

OTHER:	OTHER:	OTHER:	OTHER:
--------	--------	--------	--------

INCIDENT REPORTING

REPORTING PARTY: Brian Rodrigues	EMPLOYER: PG&E
CONTROL ROOM NOTIFIED: 779 <input checked="" type="checkbox"/> PLANT PHONE <input type="checkbox"/> OTHER <input type="checkbox"/>	
FIRE DEPT. NOTIFIED: 779 <input checked="" type="checkbox"/> PLANT PHONE <input type="checkbox"/> OTHER <input type="checkbox"/>	
WITNESS(ES): (Include Phone Number or LAN ID)	

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED: **none**

LIST FIRE FIGHTING EQUIPMENT USED: **TIC**

NARRATIVE: Responded to 779 alarm on a smell of electrical smoke in NPG Warehouse environmental room. Smell coming from room ventilation supply fan S-5. Shutdown and opened breaker to fan S-5. Smell began to diminish. Also turned off AC units 2A and 2B located on west wall of environmental room. Contacted Joe Higgins (4103) to have A&J refrigeration come out for repair. Warehouse supervisor Brian Rodrigues confirmed via phone from Higgins that A&J are on their way out to repair as of 2000 hrs.

INCIDENT DOCUMENTATION

NOTIFICATION NO.(S): **50210717** *DA = 502210994*

OTHER REPORTS:

REPORT COMPLETED BY:
FC - CAPPELLUTI, Tony M.

NAME	DATE	SIGNATURE	REVIEWER/DATE
------	------	-----------	---------------

ICS POSITIONS

FC - SCHROEDER, David H.

INCIDENT COMMANDER

CDF UNIFIED COMMAND

FC - ELLIS, Scott

SAFETY OFFICER
SECURITY LIAISON

OPERATIONS	PLANNING	LOGISTICS	MEDICAL
HM GROUP SUP	SITE ACCESS	ENTRY TEAM LDR.	Rob Gagne DECON TEAM LDR.
HM SAFETY	ENTRY TEAM	BACKUP TEAM	OTHER:

MONITORING

TIME:						
O ₂ %						
L.E.L. %						
pH:						
Chem. A:						
Chem. B:						

INCIDENT REPORTING

REPORTING PARTY: **Unknown** EMPLOYER:

CONTROL ROOM NOTIFIED: 779 PLANT PHONE OTHER

FIRE DEPT. NOTIFIED: 779 PLANT PHONE OTHER **Phone Call**

WITNESS(ES):
(Include Phone Number or LAN ID)

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED:

LIST FIRE FIGHTING EQUIPMENT USED:

NARRATIVE: Called by Control Room to investigate possible hazmat on access road between the one and three mile marker. Arrived on scene at 2.3 mile marker and found non-injury / non-emergency spill of appx 10 - 15 gallons of sulphuric acid. RQ is 1000 pounds. A hazwaste truck was hauling the batteries offsite for disposal. While navigating the turn the batteries shifted on the pallet and tipped over. The acid had spilled onto the dirt directly next to the pavement. Environmental Ops originally requested remediation back to clean dirt. Environmental Ops arrived on scene later and determined that neutralization would be acceptable. Acid neutralized with sodium bicarbonate. Scene secured at 1600

INCIDENT DOCUMENTATION

NOTIFICATION NO.(S): **50230539** *DA - 50231396*

OTHER REPORTS:

REPORT COMPLETED BY:

FC - SCHROEDER, David H.

04-06-09

NAME

DATE

SIGNATURE

REVIEWER/DATE



Diablo Canyon Fire Department Fire Incident Report

INCIDENT NO. 09-041	DATE: 6/2/09	INCIDENT TIMELINE	
LOCATION: Unit 1 Containment		NOTIFICATION: 0100 HRS.	
		AT SCENE: 0115 HRS.	
		EXTINGUISHED: 0100 HRS.	
		AVAILABLE: 0330 HRS.	
UNIT: 1 <input checked="" type="checkbox"/> 2 <input type="checkbox"/> COMMON <input type="checkbox"/>		REFLASH WATCH? N <input type="checkbox"/> Y <input checked="" type="checkbox"/>	TIME: 0000 HRS.
NON-PB <input type="checkbox"/> OUTSIDE PA <input type="checkbox"/>		REFLASH WATCH TERMINATED: HRS.	
INCIDENT TYPE: <input type="checkbox"/> STRUCTURE <input type="checkbox"/> WILDLAND <input type="checkbox"/> VEHICLE <input type="checkbox"/> SMOKE REPORT			
<input checked="" type="checkbox"/> OTHER (specify) Fire Alarm			

INCIDENT DATA		
FIRE AREA/ZONE: 9-B	OCCUPANCY: N/A	ORIGIN: N/A
CAUSE OF FIRE: N/A	WHAT BURNED: N/A	
ESTIMATED PROPERTY LOSS: None	DAMAGE TO: Nothing	
COMMAND POST LOCATION: Not est.	STAGING AREA LOC.: Not est.	
AGENCIES NOTIFIED: None		

RESPONDERS AT SCENE	
FIRE PERSONNEL: FC - CARTER, Eric J. FF - COITO, Scott T.	BRIGADE MEMBERS: NONE
	OPS RESPONDER: None
	SAFETY PERSONNEL: N/A
OFFSITE FIRE: None	SECURITY: None
	MEDICAL: None
	SL AMBULANCE: None
OTHER (specify):	

ICS POSITIONS

[]
[]

INCIDENT COMMANDER
CDF UNIFIED COMMAND

[]
[]

SAFETY OFFICER
SECURITY LIAISON

OPERATIONS	PLANNING	LOGISTICS	MEDICAL
OTHER:	OTHER:	OTHER:	OTHER:

INCIDENT REPORTING

REPORTING PARTY: **Plany System** EMPLOYER:
CONTROL ROOM NOTIFIED: 779 PLANT PHONE OTHER **Plant System**
FIRE DEPT. NOTIFIED: 779 PLANT PHONE OTHER **Pager**
WITNESS(ES): **None**
(Include Phone Number or LAN ID)

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED: **Unit 1 Detection System**
LIST FIRE FIGHTING EQUIPMENT USED: **None**
NARRATIVE: **Received a page from the U1 SFM regarding a fire alarm in containment. Only one detector was activated with no increase on the containment temp monitor. Asked for our assistance to make an entry as Operations was very low on personnel. Two FD members and one RP tech made entry and confirmed no fire or smoke in detector vacinity. Detector was A12-12 located in the overhead on the 117' at 245 degrees. Operations attempted to reset detetor. Detector reset, but went back into alarm a couple minutes later. Due to no smoke, heat, or flame, cause is possibily a bad detector. FD and RP exited containment.**

INCIDENT DOCUMENTATION

NOTIFICATION NO.(S): **50243611**
OTHER REPORTS:

REPORT COMPLETED BY:

FC - CARTER, Eric J.	6-2-09		
NAME	DATE	SIGNATURE	REVIEWER/DATE



Diablo Canyon Fire Department Fire Incident Report

INCIDENT NO. 09-042		DATE: 6/3/09		INCIDENT TIMELINE	
LOCATION: Admin 3 rd floor			NOTIFICATION: HRS.		
			AT SCENE: HRS.		
			EXTINGUISHED: HRS.		
UNIT: 1 <input type="checkbox"/> 2 <input type="checkbox"/> COMMON <input type="checkbox"/>			AVAILABLE: HRS.		
NON-PB <input checked="" type="checkbox"/> OUTSIDE PA <input type="checkbox"/>			REFLASH WATCH? N <input type="checkbox"/> Y <input checked="" type="checkbox"/> TIME: HRS.		
			REFLASH WATCH TERMINATED: HRS.		
INCIDENT TYPE: <input checked="" type="checkbox"/> STRUCTURE <input type="checkbox"/> WILDLAND <input type="checkbox"/> VEHICLE <input type="checkbox"/> SMOKE REPORT					
<input type="checkbox"/> OTHER (specify)					
INCIDENT DATA					
FIRE AREA/ZONE:		OCCUPANCY:		ORIGIN: none	
CAUSE OF FIRE: none			WHAT BURNED: none		
ESTIMATED PROPERTY LOSS: none			DAMAGE TO: none		
COMMAND POST LOCATION: none			STAGING AREA LOC.: none		
AGENCIES NOTIFIED: none					
RESPONDERS AT SCENE					
FIRE PERSONNEL: FC - STOCKS, Daniel T. FC - CAPPELLUTI, Tony M. FF - FRAZIER, Daniel F. FF - TURNER, Mark A. FF - WIMBERLY, Ivan G.			BRIGADE MEMBERS: NONE		
			OPS RESPONDER:		
			SAFETY PERSONNEL: N/A		
OFFSITE FIRE: N/A			SECURITY: N/A		
			MEDICAL: N/A		
			SL AMBULANCE:		
OTHER (specify): N/A					

ICS POSITIONS

FC - STOCKS, Daniel T.
none

INCIDENT COMMANDER

CDF UNIFIED COMMAND

none
none

SAFETY OFFICER
SECURITY LIAISON

none	none	none	none
OPERATIONS	PLANNING	LOGISTICS	MEDICAL

none	none	none	none
OTHER:	OTHER:	OTHER:	OTHER:

INCIDENT REPORTING

REPORTING PARTY: Smoke Detector	EMPLOYER:
CONTROL ROOM NOTIFIED: 779 <input type="checkbox"/> PLANT PHONE <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Fire Computer	
FIRE DEPT. NOTIFIED: 779 <input checked="" type="checkbox"/> PLANT PHONE <input type="checkbox"/> OTHER <input type="checkbox"/>	
WITNESS(ES): (Include Phone Number or LAN ID)	

LIST FIRE PROTECTION OR DETECTION SYSTEM(S) ACTIVATED: **Admin Fire Alarm Panel**

LIST FIRE FIGHTING EQUIPMENT USED: **none**

NARRATIVE: Fire Alarm was sounded for a smoke detector activation in the Admin Bldg 3rd Floor East. Security was in the area and reported no sign of smoke or fire. Building was evacuated. Fire Department personnel were next door and responded immediately. Capt. Cappelluti searched the Third Floor and found an activated smoke detector in Room 320. The room is under construction and dust from the construction activities set off the smoke detector. The alarm was reset and building occupants were allowed to return to work. Construction personnel were briefed about covering smoke detectors while work was being performed that could cause dust.

INCIDENT DOCUMENTATION

NOTIFICATION NO.(S):
OTHER REPORTS:

REPORT COMPLETED BY:
FC - STOCKS, Daniel T. **6-3-09**

NAME	DATE	SIGNATURE	REVIEWER/DATE
------	------	-----------	---------------